

SHOCK ABSORBER

**UPGRADE YOUR RIDE
WITH PROVEN
PERFORMENS**



2026

Oil shock absorbers COMFORT series

ABSEL COMFORT Hydraulic Shock Absorbers

Provide a high level of comfort and stability on any road. Equipped with a range of advanced technologies, these shock absorbers deliver improved performance and durability.

- High-quality oil: Enhances lubrication, ensuring durability and stable operation.
- Efficient stabilizing valve: Guarantees optimal tire-road contact, increasing safety and handling.
- Sintered metal piston: Improves durability and efficiency of the shock absorbers.
- Constantly active adjustment disc: Continuously adjusts comfort and stability parameters, adapting to changing road conditions.
- Original oil scraper ring: Reduces friction between moving parts, ensuring smooth operation and reduced wear.
- Chromed piston rod: Features high manufacturing precision and corrosion resistance.
- High-precision working cylinder: Reinforced construction strength extends the shock absorber's lifespan.
- DU bushing with minimal friction: Further increases strength and reduces friction at critical points of the shock absorber.



These shock absorbers are perfect for drivers seeking maximum comfort and handling for their vehicle.

ABSEL

Power in Motion. Quality in Parts.

Gas Shock absorbers PERFECT series

ABSEL PERFECT High-Pressure Monotube Gas Shock Absorbers

- **Dual-Chamber Design.** The shock absorbers feature a floating piston that separates the fluid and gas chambers. The fluid chamber is filled with oil, while the gas chamber contains nitrogen under pressure, ensuring optimal pressure and efficiency.
- **Multi-Stage Valve Mechanism.** Allows precise adjustment of damping force according to different speed conditions, improving vehicle stability and handling.
- **Flexible Oil Seal Design.** Increases sealing reliability and extends its lifespan, preventing leaks and wear.
- **Aluminum Seal Guide Components.** The use of aluminum with excellent thermal conductivity promotes better heat dissipation and increases seal durability.
- **Smooth Floating Piston Movement.** Ensures excellent response to changes in road surface, enhancing driving comfort.
- **Optimized Heat Dissipation.** The unique design with a single-wall tube between the oil and external environment improves heat dissipation, contributing to the shock absorber's long lifespan.
- **Separation of Oil and Gas.** Prevents defects in the gas path and insufficient oil compensation, which can lead to noise, reduced comfort, and degraded handling.



ABSEL PERFECT shock absorbers provide the highest level of performance and durability, making every ride more comfortable and controlled.

ABSEL

Power in Motion. Quality in Parts.

Gas Shock absorbers ADAPT series

Modern technologies and high-quality materials used in the ADAPT series gas shock absorbers provide a high level of comfort and stability on any road:

- Efficient stabilizing valve: Guarantees optimal tire-road contact, increasing safety and handling.
- Chromed piston rod: Features high manufacturing precision and corrosion resistance.
- High-precision working cylinder: Reinforced construction strength extends the shock absorber's lifespan.
- Nitrogen: Enhances damping efficiency.
- Anti-leak piston seal ring system: Prevents leaks and increases lifespan.
- Flexible valve plates and check valve: Ensure smoothness and precision of adjustments.
- Sintered piston and compression valve: Improve durability and performance.



These shock absorbers are perfect for drivers seeking maximum comfort and handling for their vehicle.

ABSEL

Power in Motion. Quality in Parts.



Shock absorber ADVANT series

ABSEL ADVANT Magnetorheological Shock Absorbers

Fast and Precise Adaptation

ABSEL ADVANT shock absorbers can instantly react to changes in road conditions, adjusting suspension stiffness within milliseconds. This ensures an exceptional level of comfort and stability, allowing drivers to feel more confident and comfortable in any situation.

Improved Durability and Reliability

With a minimal number of moving parts and advanced technological design, ABSEL ADVANT magnetorheological shock absorbers require less maintenance and have a longer service life. This reduces overall vehicle ownership and maintenance costs.

High Handling Efficiency

The ABSEL shock absorber system offers better control over the vehicle, reducing body roll during sharp turns and maneuvers, which is crucial for safety and comfort while driving.



ABSEL ADVANT shock absorbers are perfect for drivers seeking an advanced technological solution to improve their vehicle's handling and comfort.

SHOCK ABSORBER



ABSEL SKU	Description	OEM No.	Suitable for
CT342089	Shock Absorber	5206QE, 5206NH, 9674785480	PEUGEOT 308 I (4A_, 4C_) 04/12->
CT342081	Shock Absorber	5206QZ, 5206QY, 5206HT, 5206RC, 9807773580	CITROËN C4 GRAND PICASSO I (UA_) 10/06-> CITROËN C4 PICASSO I (UD_) 07/08-> CITROËN DS5 11/11-> PEUGEOT 5008 (0U_, 0E_) 09/09->
CN342023	Shock Absorber	55310H5050, 55310H5000, 553101G210, 553101G220, 55310H0000	HYUNDAI SOLARIS (HCR, HCI) 01/17-> KIA RIO II (JB) 03/05-> KIA STONIC (YB) 11/18-> KIA RIO IV (SC, FB) 07/17->
WG342009	Shock Absorber	3Q0413032, 3Q0413032A, 5Q0413031FL, 5QF413032A, 3Q0413031AK	SKODA OCTAVIA III (5E3, NL3, NR3) 01/14-> VW TIGUAN (AD1, AX1) 05/16-> SKODA KAROQ (NU7, ND7) 07/17-> SKODA KODIAQ I (NS6, NS7, NV7) 10/16->
LR342022	Shock Absorber	LR047322, LR047132, LR045269, LR045270, LR095873	LAND ROVER RANGE ROVER SPORT II (L494) 04/13->
DW342030R	Shock Absorber	96316746, 96336490	DAEWOO MATIZ (M100, M150) 09/98->
LR342016L	Shock Absorber	LR023580, LR034270, LR012997, LR020528, LR02358	LAND ROVER RANGE ROVER IV (L405) 08/12-> LAND ROVER RANGE ROVER SPORT II (L494) 04/13-> LAND ROVER RANGE ROVER III (L322) 07/10->
MS342039	Shock Absorber	A2513203131, 2513200431, 2513203131, 2513200931, A2513200931	MERCEDES-BENZ R-CLASS (W251, V251) 07/05->
CT342055	Shock Absorber	5206NF, 5206NG, 5206SF, 5206PK	PEUGEOT 308 I (4A_, 4C_) 09/07-> PEUGEOT 308 CC (4B_) 06/09->
GM342147	Shock Absorber	0436414, 436414, 13234170	OPEL INSIGNIA A (G09) 07/08->
LA342073	Shock Absorber	21700291540210, 21082915004, 21700291500400, 21102915004, 21700291540290	LADA PRIORA (2170_) 04/07-> LADA SAMARA (2109, 2115) 01/00-> LADA SAMARA (2108, 2109, 2113, 2114) 04/96-> LADA 110 (2110) 01/95->
LR342015R	Shock Absorber	LR034265, LR023573, LR012995, LR020529, LR012996	LAND ROVER RANGE ROVER IV (L405) 08/12-> LAND ROVER RANGE ROVER III (L322) 07/10->
NS342423	Shock Absorber	562102F025, 5620082NX6, 562102F000	NISSAN PRIMERA (P11) 09/96-> NISSAN PRIMERA (WP11) 08/99->
CT342093	Shock Absorber	5206YQ, 5206QH, 5206QQ, 5206QJ, 5206QR	PEUGEOT PARTNER 04/08-> CITROËN BERLINGO (B9) 04/08-> CITROËN BERLINGO / BERLINGO FIRST (M_) 01/10->
VL342065	Shock Absorber	271105, 1273915, 274040, 1387718, 1229690	VOLVO 940 (944) 08/90-> VOLVO 960 II (964) 07/94-> VOLVO 740 (744) 08/87-> VOLVO 940 II (944) 08/94->
HY342051	Shock Absorber	553004L002, 553004L001, 553004L000, 553001K000, 553001J000	HYUNDAI SOLARIS (RB) 11/10-> KIA RIO III (UB) 06/12-> KIA VENGA (YN) 02/10-> HYUNDAI i20 I (PB, PBT) 09/08->
GM342245R	Shock Absorber	95137366, 95353837, 344914	OPEL MOKKA / MOKKA X (J13) 01/13-> CHEVROLET TRAX 03/13->
DW342038R	Shock Absorber	96300280, 96289902, 96298717	DAEWOO NUBIRA (J100) 05/97-> DAEWOO NUBIRA (J150) 06/99->
GM342107	Shock Absorber	95077490, 436388, 93189036	OPEL CORSA D (S07) 07/06-> FIAT GRANDE PUNTO (199_) 06/05-> FIAT PUNTO (199_) 03/12-> ABARTH GRANDE PUNTO 07/07->
DW342036R	Shock Absorber	96980825, 96980827, 96653232	CHEVROLET AVEO / KALOS (T250, T255) 09/08-> ZAZ VIDA (SF6_, SA6_) 01/12-> ZAZ VIDA (SF4_, SA4_) 01/12->
SZ342137L	Shock Absorber	4160264J00, 4160278K11, 4160265J00, 4160264J01, 4160265J01	SUZUKI GRAND VITARA II (JT, TE, TD) 10/05->
WG342138	Shock Absorber	5N0413031AK, 5N0413031AC, 5N0413031AL, 7N0413031J, 7N0413031K	SKODA OCTAVIA II (1Z3) 06/04-> VW JETTA IV (162, 163, AV3, AV2) 12/11-> VW TIGUAN (5N_) 09/07-> VW PASSAT B7 (362) 02/11->
DW342033L	Shock Absorber	96336487, 96336488	CHEVROLET SPARK 05/05-> CHEVROLET MATIZ (M200, M250) 03/05->
KI342098R	Shock Absorber	54661A7CA0, 54661A7400, 54661A7100, 54661A7200, 54661B0FA0	KIA CERATO III (YD) 07/16->
DW342032R	Shock Absorber	96316746, 96336490	DAEWOO MATIZ (M100, M150) 09/98-> CHEVROLET SPARK 05/05-> CHEVROLET MATIZ (M200, M250) 03/05->
HY342202L	Shock Absorber	546513Z320, 546513Z920, 546513Z120, 546513Z700, 546513Z130	HYUNDAI i40 I (VF) 10/12-> HYUNDAI i40 I CW (VF) 10/12->
DW342031L	Shock Absorber	96336487, 96336488	DAEWOO MATIZ (M100, M150) 09/98->
KI342104R	Shock Absorber	546611M300, 546611M310, 546611M360, 546611M000, 546611M100	KIA CERATO II (TD) 01/10->
DW342025L	Shock Absorber	96336487, 96336488	DAEWOO MATIZ (M100, M150) 09/98->
CT342103	Shock Absorber	5206TR, 1371413080, 1362548080, 1355821080, 1352281080	PEUGEOT BOXER 03/11-> FIAT DUCATO (250_) 08/06-> CITROËN JUMPER III 07/11->
CT342107R	Shock Absorber	9806013280, 9805824380, 9819219080, 9819233680, 9810768580	CITROËN C-ELYSEE (DD_) 11/12-> PEUGEOT 301 11/12->

SHOCK ABSORBER



TY342017	Shock Absorber	4853069535, 4853069205, 4853080816, 4853060210, 4853060400	TOYOTA LAND CRUISER PRADO (_J15_) 08/09-> TOYOTA LAND CRUISER PRADO (_J12_) 12/02-> LEXUS GX (URJ15_, GRJ15_) 01/10-> LEXUS GX (_J12_) 11/01->
CT342092	Shock Absorber	9678509980, 9678510180, 9678510080, 9807784280, 9807784080	PEUGEOT PARTNER TEPEE 04/08-> CITROËN BERLINGO MULTISPACE (B9) 04/08-> CITROËN DS5 11/11-> DS DS 5 (KF_) 04/15->
CT342159L	Shock Absorber	4060A173, 5202NZ, 5202ZP, 5202ZN, 5208S0	MITSUBISHI OUTLANDER II (CW_W) 09/07-> PEUGEOT 4007 (VU_, VV_) 02/07-> CITROËN C-CROSSER (VU_, VV_) 08/08->
CT342203	Shock Absorber	1351194080, 5202J3, 5208G8, 5202J0, 1334894080	FIAT DUCATO (244_) 12/01-> FIAT DUCATO (250_) 08/06-> CITROËN JUMPER II (244, Z_) 04/02-> FIAT DUCATO (230_) 08/94->
HY342082R	Shock Absorber	546601G200, 546601E200, 546601E000, 546601G400, 546601E100	KIA RIO II (JB) 03/05-> HYUNDAI ACCENT III (MC) 11/05->
GM342208L	Shock Absorber	96289901, 96300279, 96298716	DAEWOO NUBIRA (J100) 05/97-> DAEWOO NUBIRA (J150) 06/99->
DW342020	Shock Absorber	96342033, 96316781, S112915010	DAEWOO MATIZ (M100, M150) 09/98->
MT342159L	Shock Absorber	4060A242	MITSUBISHI LANCER VIII (CY_A, CZ_A) 06/08-> MITSUBISHI LANCER VIII (CX_A) 06/08->
DW342024R	Shock Absorber	96316746, 96336490	DAEWOO MATIZ (M100, M150) 09/98->
TY342493R	Shock Absorber	4851080460, 485108Z065, 4851080336, 485108Z292, 4851080698	TOYOTA COROLLA (_E15_) 10/06-> TOYOTA AURIS (_E15_) 02/09->
CE342003	Shock Absorber	T112915010, T112915010AB, 4853149087, 4853142020, S2515200	TOYOTA RAV 4 II (_A2_) 05/00-> CHERY TIGGO 06/11-> TOYOTA RAV 4 I (_A1_) 06/94-> CHERY TIGGO 3 05/14->
CT342054	Shock Absorber	5206EK, 5206V9, 5206W0, 5206SG, 5206CS	PEUGEOT 307 (3A/C) 08/00-> CITROËN C4 (LA_) 11/04-> CITROËN C4 I (LC_) 11/04-> PEUGEOT 308 CC (4B_) 06/09->
VL342045R	Shock Absorber	1741781, 1720984, 31429127, 31317812, 1718456	FORD MONDEO IV (BA7) 03/07-> VOLVO XC70 II (136) 08/07-> VOLVO S80 II (124) 01/10-> VOLVO S60 II (134) 05/12->
MT342188	Shock Absorber	MR244217, MR403040, MB809270, MB914897, MR244447	MITSUBISHI LANCER VI (CJ_, CP_, CK_) 12/95-> MITSUBISHI COLT V (CJ_, CP_) 05/96-> MITSUBISHI LANCER V (CB_A, CD_A, CE_A) 06/92-> MITSUBISHI COLT IV (CA_A) 04/92->
RN342063	Shock Absorber	562103901R, 562106313R, 562103841R, 562101478R, 562108189R	RENAULT LOGAN/STEPWAY II (L8_) 04/14-> RENAULT SANDERO/STEPWAY II (B8_) 04/14-> RENAULT LOGAN II (K8_) 12/13->
BW342022L	Shock Absorber	31316785529, 31316777673, 31316777671, 31316785527, 31316758883	BMW 7 (E65, E66, E67) 07/01->
FT342045	Shock Absorber	50516724, 50508841	ALFA ROMEO MITO (955_) 10/09->
BW342021R	Shock Absorber	31316785530, 31316777674, 31316777672, 31316785528, 6785528	BMW 7 (E65, E66, E67) 07/01->
HY342089R	Shock Absorber	546601G200, 546601E200, 546601E000, 546601G400, 546601E100	KIA RIO II (JB) 03/05-> HYUNDAI ACCENT III (MC) 11/05->
BW342020	Shock Absorber	33526766605, 33526785982, 33526785986, 33526785978, 33527905315	BMW 5 (E60) 04/05-> BMW 5 (E61) 01/07->
MS342100	Shock Absorber	A1663200030, A1663201130, 1663201130, A1663261500, 1663200030	MERCEDES-BENZ GLE (W166) 04/15-> MERCEDES-BENZ M-CLASS (W166) 06/11->
BW342019	Shock Absorber	31326764461, 31306775055, 31326764457, 31326764459, 31326764463	BMW 5 (E60) 04/05-> BMW 5 (E61) 09/07->
WG342061	Shock Absorber	6RU513025A, 6R0513025BA, 6RU513025B, 1J0513025DJ, 1J9513025A	VW POLO V (602, 604, 612, 614) 05/10-> SKODA RAPID (NH3, NK3, NK6) 05/15-> SKODA OCTAVIA I (1U2) 09/00-> SKODA ROOMSTER (5J7) 09/06->
BW342018	Shock Absorber	33526786541, 33526786543, 33526786542, 33526758094, 33526758095	BMW 7 (E65, E66, E67) 07/01->
WG342160	Shock Absorber	3B0413031Q, 3B0413031P, 3B0413031AB, 4B0412031CA, 4B0412031BN	VW PASSAT B5.5 (3B3) 11/00-> VW PASSAT B5 (3B2) 10/96-> AUDI A4 B5 (8D2) 11/94-> AUDI A6 C5 (4B2, 4B4) 02/97->
MZ342161R	Shock Absorber	BR5S34700A, BBM234700C, BBM234700A, BR5S34700B, BRY034700	MAZDA 3 (BK) 02/04-> MAZDA 3 (BL) 12/08-> MAZDA 5 (CR) 02/05->
HY342195R	Shock Absorber	546612S000, 546612Y360, 546612Y610, 546613U000, 546612Y500	KIA SPORTAGE III (SL) 06/10-> HYUNDAI ix35 (LM, EL, ELH) 08/09->
CT342102	Shock Absorber	5206QZ, 5206QY, 5206HT, 5206RC, 9807773580	CITROËN C4 GRAND PICASSO I (UA_) 10/06-> CITROËN C4 PICASSO I (UD_) 07/08->
GM342314L	Shock Absorber	95948811, 95948815, 4817808	CHEVROLET CAPTIVA (C100, C140) 06/06-> OPEL ANTARA A (L07) 08/06->
MZ342082	Shock Absorber	EG2128910F, EH4628910, EH4828910A, EG2128910E, EH4828910B	MAZDA CX-7 (ER) 06/06->

SHOCK ABSORBER



MZ342091	Shock Absorber	8L8Z18125B, EC0128700K, 7L8Z18125AB, E18128700B	FORD MAVERICK 03/04-> MAZDA TRIBUTE (EP) 04/04->
BW342030R	Shock Absorber	37116797028, 37116797026, 6797028, 6797026	BMW X3 (F25) 09/10-> BMW X4 (F26) 04/14->
BW342031L	Shock Absorber	37116797025, 37116797027, 6797027, 6797025	BMW X3 (F25) 09/10-> BMW X4 (F26) 04/14->
HY342160R	Shock Absorber	5466026300, 5466026100, 5466026000, 5466026200	HYUNDAI SANTA FÉ I (SM) 02/01->
VL342041R	Shock Absorber	31277200, 31340322, 31329495, 31262895, 31304052	FORD MONDEO IV (BA7) 03/07-> VOLVO XC70 II (136) 08/07-> VOLVO S80 II (124) 01/10-> VOLVO V70 III (135) 08/07->
TY342603R	Shock Absorber	4853089025, 4853080527, 4853009K70, 4853009N60, 4853009M20	TOYOTA CAMRY (V4_) 01/06-> LEXUS ES (V4_) 05/06->
MS342040	Shock Absorber	A2113262800, A2193260400, A2113260100, A2113200631, A2113200731	MERCEDES-BENZ E-CLASS (W211) 03/02-> MERCEDES-BENZ CLS (C219) 10/04->
WG342114	Shock Absorber	1K0413031BK, 5C0413031J, 1K0413031BF, 1K0413031CL, 1K0413031BA	SKODA OCTAVIA II (1Z3) 06/04-> VW JETTA IV (162, 163, AV3, AV2) 12/11-> SKODA YETI (5L) 09/09-> VW JETTA III (1K2) 09/04->
HY342161L	Shock Absorber	5465026300, 5465026000, 5465026100, 5465026200	HYUNDAI SANTA FÉ I (SM) 02/01->
HY342090L	Shock Absorber	546501G200, 546501E200, 546501E000, 546500M500, 546501G400	KIA RIO II (JB) 03/05-> HYUNDAI ACCENT III (MC) 11/05->
HY342174L	Shock Absorber	546502B200, 546502B201, 546500W001, 546502B001, 546602B000	HYUNDAI SANTA FÉ II (CM) 01/09->
BW342161L	Shock Absorber	31326764461, 31306775055, 31326764457, 31326764459, 31326764463	BMW 5 (E60) 03/05-> BMW 5 (E61) 09/07->
MZ342183R	Shock Absorber	BR5S34700A, BBM234700C, BBM234700A, BR5S34700B, BRY034700	MAZDA 3 (BK) 02/04-> MAZDA 3 (BL) 12/08-> MAZDA 5 (CR) 02/05->
HN342254	Shock Absorber	52611SWAA02, 52611SWAA01, 52610SXSA15, 52611SWA01, 52611SWA02	HONDA CR-V III (RE_) 09/09-> HONDA CR-V II (RD_) 09/01->
HY342173R	Shock Absorber	546602B200, 546602B201, 546502B000, 546602B001, 546600W001	HYUNDAI SANTA FÉ II (CM) 01/09->
BW342062	Shock Absorber	33526771725, 33526771555, 33526796157, 33526779985, 33526796161	BMW 3 (E90) 09/07-> BMW 1 (E81) 09/07-> BMW 1 (E87) 06/04-> BMW 3 (E92) 06/07->
MT342171	Shock Absorber	MN101958, MN184083	MITSUBISHI LANCER VII (CS_W, CT_W) 09/03-> MITSUBISHI LANCER VII (CS_A, CT_A) 12/03->
TY342746	Shock Absorber	4851069545, 4851069305, 4851069165, 4851069525, 4851080086	TOYOTA LAND CRUISER PRADO (J12_) 12/02-> LEXUS GX (J12_) 11/01-> TOYOTA 4 RUNNER IV (N21_) 01/03-> TOYOTA (FAW) PRADO (J12_) 10/03->
NS342414	Shock Absorber	5621095F0B, 562104M427, 562104M426, 562105M425, 562104M425	NISSAN ALMERA Classic (B10) 03/06-> NISSAN ALMERA II (N16) 07/00->
HY342063	Shock Absorber	55310M0000, 55307BW000, 55300C9000, 55300M0000, 55310M4000	HYUNDAI CRETA 01/16->
MZ342184L	Shock Absorber	BR5S34900A, BBM234900C, BBM234900A, BRY034900, BR5V34900A	MAZDA 3 (BK) 02/04-> MAZDA 3 (BL) 12/08-> MAZDA 5 (CR) 02/05->
GM342290L	Shock Absorber	13412718, 13412716, 13331986	CHEVROLET CRUZE (J300) 05/09-> CHEVROLET CRUZE (J305) 01/12->
MT342190	Shock Absorber	4162A130, 4162A245, 4162A304, 4162A239, 4162A034	MITSUBISHI OUTLANDER III (GG_W, GF_W, ZJ, ZL, ZK) 10/12-> MITSUBISHI ASX (GA_W_) 06/10-> MITSUBISHI OUTLANDER II (CW_W) 09/07-> PEUGEOT 4008 05/12->
WG342134	Shock Absorber	3C0413031BA, 5N0413031AE, 3C0413031BC, 3C0413031AT, 1T0413031HP	SKODA OCTAVIA II (1Z3) 06/04-> VW JETTA IV (162, 163, AV3, AV2) 12/11-> VW TIGUAN (5N_) 09/07-> SKODA YETI (5L) 09/09->
MS342149	Shock Absorber	A9013200631, A9013200731, 2D0513029P, A9013200431, A9033200131	MERCEDES-BENZ SPRINTER CLASSIC 3,5-t (B909) 09/13-> VW CRAFTER 30-50 (2E_) 04/06-> VW CRAFTER 30-35 (2E_) 04/06-> MERCEDES-BENZ SPRINTER 2-t (B901, B902) 02/95->
HY342182L	Shock Absorber	54651M0000, 54651M0200, 54651M0100, 54651M4000, 54651M4500	HYUNDAI CRETA 01/16->
WG342057	Shock Absorber	3B5513031B, 3B9513031G, 4B0513032D, 3B5513031E, 3B0513031P	VW PASSAT B5.5 (3B3) 11/00-> VW PASSAT B5 (3B2) 10/96-> AUDI A6 C5 (4B2, 4B4) 02/97-> SKODA SUPERB I (3U4) 12/01->
MZ342216R	Shock Absorber	GS1D34700G, GS1D34700F, GS1D34700E, GS3L34700B, GS1D34700D	MAZDA 6 (GH) 08/07->
MT342199	Shock Absorber	4162A184, MR589026, MN101601, MN101960, MR961212	MITSUBISHI LANCER VII (CS_A, CT_A) 09/03-> MITSUBISHI LANCER VII (CS_W, CT_W) 09/03->
WG342116	Shock Absorber	6RU413031B, 6R0413031BF, 6R0413031AJ, 6RF413031F, 6R0413031AT	VW POLO V (602, 604, 612, 614) 05/10-> SKODA RAPID (NH3, NK3, NK6) 05/15-> VW POLO V (6R1, 6C1) 03/09-> AUDI A1 (8X1, 8XK) 05/10->
HY342168L	Shock Absorber	546502B200, 546502B201, 546502B001, 546602B000	HYUNDAI SANTA FÉ II (CM) 07/10->

SHOCK ABSORBER



HY342196L	Shock Absorber	546512S000, 546513U000, 546512Y610, 546512Y360, 546512Y500	KIA SPORTAGE III (SL) 06/10-> HYUNDAI ix35 (LM, EL, ELH) 08/09->
RN342099	Shock Absorber	562108593R, 562104554R, 562108685R, 562100026R, 562100022R	RENAULT MEGANE III (BZ0/1_, B3_) 11/08-> RENAULT MEGANE III (DZ0/1_) 11/08-> RENAULT MEGANE CC (EZ0/1_) 06/10->
MT342221	Shock Absorber	MR992321, 4062A099, 4062A031, 4062A081, MR992320	MITSUBISHI L200 / TRITON (KA_T, KB_T) 11/05-> MITSUBISHI L200 / TRITON (KJ_, KK_, KL_) 09/15->
HY342154R	Shock Absorber	546612E500, 546612E201, 546611F000	HYUNDAI TUCSON (JM) 08/04-> KIA SPORTAGE II (JE_, KM_) 09/04->
MS342098	Shock Absorber	A1643202231, A1643202631, A1643200631, A1643201331, 1643202631	MERCEDES-BENZ M-CLASS (W164) 02/05->
TY342419R	Shock Absorber	4853049165, 4853049125, 4853049195, 4853049175, 4853048020	LEXUS RX (MCU15) 01/98-> TOYOTA HIGHLANDER / KLUGER (_U2_) 06/00-> TOYOTA HARRIER (_U1_) 05/97->
HY342145L	Shock Absorber	546501R000, 546501R001, 546501W001, 546501W030, 546501R061	HYUNDAI SOLARIS (RB) 11/10-> KIA RIO III (UB) 06/12->
DW342034R	Shock Absorber	96424402, 96424026	CHEVROLET SPARK 05/05-> CHEVROLET MATIZ (M200, M250) 03/05->
MS342038	Shock Absorber	A1663200930, A1663200130, A1663201930, 1663200930, A1663261300	MERCEDES-BENZ GLS (X166) 01/17-> MERCEDES-BENZ GLE (W166) 04/15-> MERCEDES-BENZ M-CLASS (W166) 06/11-> MERCEDES-BENZ GL-CLASS (X166) 07/12->
TY342420L	Shock Absorber	4854049125, 4854049065, 4854049105, 4854049115, 4854048060	LEXUS RX (MCU15) 01/98-> TOYOTA HIGHLANDER / KLUGER (_U2_) 06/00-> TOYOTA HARRIER (_U1_) 05/97->
HY342117R	Shock Absorber	546604L101, 546604Y101, 546604L100, 546604L000, 546604Y100	KIA RIO III (UB) 06/11-> HYUNDAI SOLARIS (RB) 11/10->
WG342132	Shock Absorber	7H0413031N, 7E5413031C, 7E0413031C, 7H0413031L, 7E5413031H	VW TRANSPORTER T5 (7HA, 7HH, 7EA, 7EH) 04/03-> VW TRANSPORTER T5 (7HB, 7HJ, 7EB, 7EJ) 09/09-> VW TRANSPORTER T6 / CARAVELLE T6 (SGB, SGJ, SHB, SHJ) 08/15-> VW MULTIVAN T5 (7HM, 7HN, 7HF, 7EF, 7EM, 7EN) 09/09->
KI342042	Shock Absorber	553103E500, 553103E600	KIA SORENTO I (JC) 12/06->
KI342024	Shock Absorber	5531007100, 553001Y200, 5531007101, 55310G6200, 553001Y210	KIA PICANTO III (JA) 03/17-> KIA PICANTO I (SA) 04/04->
TY342472R	Shock Absorber	4851080287, 4851080451, 4851080284, 4851080579, 4851080637	TOYOTA RAV 4 III (_A3_) 02/06->
WG342085	Shock Absorber	5N0513049AP, 5N0513049AB, 5N0513049AG, 5N0513049L, 5N0513049AC	VW TIGUAN (5N_) 09/07-> AUDI Q3 (8UB, 8UG) 06/11->
TY342016	Shock Absorber	4851060260, 4851069476, 4851069495, 4851069475, 4851069565	TOYOTA LAND CRUISER PRADO (_J15_) 08/09-> LEXUS GX (URJ15_, GRJ15_) 01/10->
SZ342136R	Shock Absorber	4160164J00, 4160165J00, 4160178K11, 4160164J01, 4160165J01	SUZUKI GRAND VITARA II (JT, TE, TD) 10/05->
MS342126	Shock Absorber	A6393262100, A6393262400, A6393260300, A6393262500, A6393261000	MERCEDES-BENZ VITO (W639) 09/07-> MERCEDES-BENZ VIANO (W639) 07/10-> MERCEDES-BENZ VITO / MIXTO (W639) 09/03->
TY342473L	Shock Absorber	4852080074, 4852080195, 4852080299, 4852080071, 4852080340	TOYOTA RAV 4 III (_A3_) 02/06->
MZ342162L	Shock Absorber	BR5S34900A, BBM234900C, BBM234900A, BRY034900, BR5V34900A	MAZDA 3 (BK) 02/04-> MAZDA 3 (BL) 12/08-> MAZDA 5 (CR) 02/05->
MS342188	Shock Absorber	A6393206013, A6393206613, A6393207113, 6393206613, 6393206013	MERCEDES-BENZ VITO (W639) 09/07-> MERCEDES-BENZ VIANO (W639) 07/10-> MERCEDES-BENZ VITO / MIXTO (W639) 09/03->
MT342106	Shock Absorber	4162A436, 4162A023, MR566276, MR990539, 4162A437	MITSUBISHI PAJERO IV (V8_W, V9_W) 02/07->
MT342158R	Shock Absorber	4060A241	MITSUBISHI LANCER VIII (CY_A, CZ_A) 06/08-> MITSUBISHI LANCER VIII (CX_A) 06/08->
TY342322	Shock Absorber	4853069516, 4853069515, 4853060201, 4853035291, 4853060200	TOYOTA LAND CRUISER PRADO (_J15_) 08/09->
MT342105	Shock Absorber	4162A023, MR566276, MR990539, MR566275, 4162A127	MITSUBISHI PAJERO IV (V8_W, V9_W) 02/07-> MITSUBISHI PAJERO III (V7_W, V6_W) 04/00-> MITSUBISHI PAJERO III Canvas Top (V6_W, V7_W) 10/01-> MITSUBISHI PAJERO II (V3_W) 04/00->
TY342557R	Shock Absorber	4851080460, 485108Z065, 4851080336, 485108Z292, 4851080698	TOYOTA COROLLA (_E15_) 01/07-> TOYOTA COROLLA (_E18_, ZRE1_) 06/13-> TOYOTA AURIS (_E15_) 03/07-> TOYOTA AURIS (_E18_) 10/12->
MZ342186L	Shock Absorber	EH4634900, EG2134900C, EG2134900B, EG2134900A, EH1434900	MAZDA CX-7 (ER) 06/06->
SZ342068	Shock Absorber	4180080J01, 4180080J21, 4180080J20, 4180075K11, 4180075K21	SUZUKI SX4 (EY, GY) 06/06-> SUZUKI SX4 (GY, RW) 10/07->
HY342216	Shock Absorber	553113D602, 5531138601, 553113D601, 553113D600, 5531139800	HYUNDAI SONATA IV (EF) 10/01-> KIA MAGENTIS I (GD, MS) 05/01-> HYUNDAI XG (XG) 12/98-> HYUNDAI XG 10/03->
MZ342185R	Shock Absorber	EH4634700, EH4834700, EG2134700C, EG2134700B, EG2134700A	MAZDA CX-7 (ER) 06/06->
TY342604L	Shock Absorber	4854039755, 4854080010, 4854009660, 4854009810, 4854009760	TOYOTA CAMRY (_V4_) 01/06-> LEXUS ES (_V4_) 05/06->
NS342172	Shock Absorber	56210CL00J, 56210CG025, 56210CL025, 56210CG225, 56210CG725	INFINITI FX 01/03->
WG342133	Shock Absorber	A9043201930, A9043201630, 2D0413029A, A9043200830, A9043200730	MERCEDES-BENZ SPRINTER CLASSIC 4,6-t (B909) 09/13-> MERCEDES-BENZ SPRINTER 2-t (B901, B902) 02/95->

SHOCK ABSORBER

			MERCEDES-BENZ SPRINTER 3-t (B903) 04/00-> VW LT 28-46 II (2DC, 2DF, 2 05/99->
HY342104R	Shock Absorber	546601G200, 546601E200, 546601E000, 546601G400, 546601E100	KIA RIO II (JB) 03/05-> HYUNDAI ACCENT III (MC) 11/05->
KI342105L	Shock Absorber	546511M300, 546511M310, 546511M360, 546511M000, 546511M100	KIA CERATO II (TD) 01/10->
GM342232L	Shock Absorber	13331986, 13331988, 13402938	CHEVROLET CRUZE (J300) 05/09-> CHEVROLET CRUZE (J305) 01/12-> OPEL AMPERA (R12) 11/11->
WG342109	Shock Absorber	6Q0413031BK, 6Q0413031BJ, 6Q0413031BP, 6Q0413031BL, 443512331	SKODA FABIA II (542) 01/07-> SKODA FABIA I (6Y2) 01/03-> SKODA ROOMSTER (5J7) 09/06-> SKODA FABIA II (545) 10/07->
GM342217	Shock Absorber	22064736, 22237833, 88965469	OPEL INSIGNIA A (G09) 07/08-> CHEVROLET IMPALA 01/99->
GM342213L	Shock Absorber	96407819, 96454522	CHEVROLET LACETTI (J200) 03/05-> DAEWOO NUBIRA (J200) 07/03-> DAEWOO LACETTI (KLAN) 02/04-> CHEVROLET NUBIRA 01/06->
KI342099L	Shock Absorber	54651A7CA0, 54651A7400, 54651A7100, 54651A7200, 54651A7AB0	KIA CERATO III (YD) 07/16->
NS342404	Shock Absorber	562102F025, 562108F825, 562102F525, 5620082NX6, 562102F500	NISSAN PRIMERA (P11) 09/96->
GM342157	Shock Absorber	13279268, 13314312, 436693	CHEVROLET ORLANDO (J309) 02/11-> OPEL ZAFIRA TOURER C (P12) 10/11-> VAUXHALL ZAFIRA TOURER Mk III (P12) 02/13->
NS342311L	Shock Absorber	55303EQ025, 553038H327, 553038H326, 553038H625, 55303EQ026	NISSAN X-TRAIL I (T30) 07/01->
GM342138	Shock Absorber	93178641, 436334, 93178642, 93178640	OPEL ZAFIRA / ZAFIRA FAMILY B (A05) 07/05-> OPEL ASTRA H (A04) 09/08-> OPEL ASTRA H GTC (A04) 01/06->
GM342123	Shock Absorber	52058071, 95493855, 52016646	CHEVROLET AVEO (T300) 03/11-> CHEVROLET COBALT 01/13->
JA342004	Shock Absorber	C2D16483, C2D19108, C2D11675, C2D13345, AW9318045CA	JAGUAR XJ (X351) 10/09->
GM342106	Shock Absorber	0436414, 436414, 13234170	OPEL INSIGNIA A (G09) 07/08->
GM342104	Shock Absorber	13332639, 13412145, 22825519	CHEVROLET CRUZE (J300) 05/09-> OPEL ASTRA J (P10) 12/09-> OPEL ASTRA J 06/12-> CHEVROLET CRUZE (J305) 01/12->
VL342046L	Shock Absorber	1741782, 1721075, 31429128, 31277906, 31317797	FORD MONDEO IV (BA7) 03/07-> VOLVO XC70 II (136) 08/07-> VOLVO S80 II (124) 01/10-> VOLVO S60 II (134) 05/12->
TY342273	Shock Absorber	4853142130, 4853142300, 4853142490, 4853142230, 4853142301	TOYOTA RAV 4 IV (_A4_) 12/12-> TOYOTA RAV 4 III (_A3_) 02/06-> LEXUS NX (_Z1_) 11/14->
FR342195L	Shock Absorber	CV6Z18124AZ, 1801173, 1801172, 1801174, CV6Z18124G	FORD KUGA II (DM2) 01/14->
MZ342182L	Shock Absorber	GMM634900, GML834900A, GHP934900B, GHT634900A, GHT634900B	MAZDA 6 (GJ, GL) 12/12->
FR342194R	Shock Absorber	1801176, CV6Z18124AG, 1801175, 1801177, CV6Z18124AX	FORD KUGA II (DM2) 01/14->
FR342192L	Shock Absorber	1709759, 1710069, 1851890, 1704766, 1731863	FORD FOCUS III 07/10-> FORD C-MAX II (DXA/CB7, DXA/CEU) 12/10-> FORD GRAND C-MAX (DXA/CB7, DXA/CEU) 12/10->
NS342141	Shock Absorber	E620035G26, 5620035G26, 5620035G25, E620025G0B, 5621031G25	NISSAN NP300 PICKUP (D22) 04/08-> NISSAN NAVARA (D22) 11/01-> NISSAN PICK UP (D21) 03/86-> NISSAN PICK UP (D22) 03/02->
SY342005	Shock Absorber	4530134100, 4530134000, 4531034000	SSANGYONG ACTYON II 08/12-> SSANGYONG KORANDO (CK) 02/12->
HY342227	Shock Absorber	5461138610, 546113F400, 5461138611	HYUNDAI SONATA IV (EF) 06/98-> HYUNDAI XG (XG) 12/98->
TY342744	Shock Absorber	4851069645, 4851069485, 4851080671, 4851080507, 4851069465	TOYOTA LAND CRUISER PRADO (_J15_) 08/09->
HY342118L	Shock Absorber	546504L101, 546504Y101, 546504L100, 546504L000, 546504Y100	KIA RIO III (UB) 06/11-> HYUNDAI SOLARIS (RB) 11/10->
MS342171	Shock Absorber	A1693200530, A1693201630, A1693200130, A1693201730, A1693200430	MERCEDES-BENZ A-CLASS (W169) 04/09-> MERCEDES-BENZ B-CLASS (W245) 04/09->
RN342064	Shock Absorber	562103901R, 562106313R, 562103841R, 8200647880, 562101478R	RENAULT LOGAN I (LS_) 09/04-> RENAULT SANDERO/STEPWAY I (BS_) 02/09->
RN342088	Shock Absorber	562108593R, 562104554R, 562108685R, 562100026R	RENAULT MEGANE III (KZ0/1) 02/09-> RENAULT MEGANE III (BZ0/1_, B3_) 11/08-> RENAULT MEGANE III (DZ0/1_) 11/08->
HY342221	Shock Absorber	553112H000, 553112H201, 553112H100, 553002H000, 553112H101	HYUNDAI ELANTRA IV (HD) 06/06->
HY342050	Shock Absorber	5530526200, 5530526000	HYUNDAI SANTA FÉ I (SM) 02/01->
MT342217	Shock Absorber	4062A022, 4062A087, 4062A085, NSFCW6WFRT, GL13285	MITSUBISHI PAJERO SPORT II (KH_, KG_) 07/08->
HY342144R	Shock Absorber	546601R000, 546601R001, 546601W030, 546601R061, 546601W000	HYUNDAI SOLARIS (RB) 11/10-> KIA RIO III (UB) 06/12->
HN342176	Shock Absorber	52611S10A01, 52610S10A01, 52611S10024	HONDA CR-V I (RD) 01/99->
WG342131	Shock Absorber	A9013201530, A9013202130, 2D0413029, A9013200330, A9013200830	MERCEDES-BENZ SPRINTER CLASSIC 3,5-t (B909) 09/13-> MERCEDES-BENZ SPRINTER 2-t (B901, B902) 02/95->

SHOCK ABSORBER



			MERCEDES-BENZ SPRINTER 3-t (B903) 04/00-> VW LT 28-35 II (2DB, 2DE, 2DK) 05/99->
RN342059	Shock Absorber	6001549248, 8200417472, 8200417472C	RENAULT LOGAN I (LS_) 09/04-> RENAULT SANDERO/STEPWAY I (BS_) 02/09->
GM342333	Shock Absorber	96445038, 96226992	DAEWOO NEXIA 02/95-> DAEWOO LANOS (KLAT) 05/97-> DAEWOO ESPERO (KLEJ) 02/95-> OPEL KADETT E (T85) 09/84->
TY342558L	Shock Absorber	4852080203, 4852009Y20, 4852080110, 485208Z150, 4852080392	TOYOTA COROLLA (E15_) 01/07-> TOYOTA COROLLA (E18_, ZRE1_) 06/13-> TOYOTA AURIS (E15_) 03/07-> TOYOTA AURIS (E18_) 10/12->
HN342219	Shock Absorber	52611SEAE04, 52611SEAE03, 52611SEFE02, 52611SEFE01, 52611SDBA03	HONDA ACCORD VII (CL, CN) 02/03->
HY342109L	Shock Absorber	5535117600, 5535117500, 5535117200, 5535117630, 5535117100	HYUNDAI MATRIX (FC) 06/01->
HN342046	Shock Absorber	52610SZA04, 52610SZA05	HONDA PILOT 01/11->
GM342289R	Shock Absorber	13412719, 13412717, 13331989	CHEVROLET CRUZE (J300) 05/09-> CHEVROLET CRUZE (J305) 01/12->
TY342182	Shock Absorber	4853180508, 4853180102, 4853180083, 4853180509, 4853180089	TOYOTA 4 RUNNER II (N13_) 01/90-> TOYOTA HILUX VI (N1_) 08/98-> TOYOTA HILUX V (N8_, N9_, N10_, N11_) 01/89->
GM342266	Shock Absorber	5066337AA, 5066333AA, 5066336AA, 5066338AA, 05066337AA	DODGE CARAVAN (RG_) 02/00-> CHRYSLER VOYAGER IV (RG, RS) 04/03->
NS342409	Shock Absorber	5621095F0B, 562104M427, 562104M426, 562105M425, 562104M425	NISSAN ALMERA Classic (B10) 03/06-> NISSAN ALMERA II (N16) 07/00->
RN342062	Shock Absorber	8200953294, 8200742812, 5621000Q2H, 5621000Q3F, 6001547072	RENAULT LOGAN I (LS_) 09/04-> LADA LARGUS (KS0_, RS0_, KSA_) 09/17-> RENAULT SANDERO/STEPWAY I (BS_) 02/09-> RENAULT LOGAN I (KS_) 10/07->
FR342075	Shock Absorber	1605790, 1676745, 1605788, 1605791, 1605792	FORD TRANSIT (FA_) 10/11-> FORD TRANSIT (FD_, FB_, FS_, FZ_, FC_) 04/06-> FORD TRANSIT (FM_, FN_, F) 10/11-> FORD TRANSIT TOURNEO 07/06->
MT342118	Shock Absorber	MR519614	MITSUBISHI LANCER VII (CS_A, CT_A) 09/03-> MITSUBISHI LANCER VII (CS_W, CT_W) 09/03->
SU342132	Shock Absorber	20365XA01A, 20379XA00A, 20365XA00A, 20365XA03A, 20365XA04A	SUBARU TRIBECA (B9) 09/07->
HY342226	Shock Absorber	546113K770, 546113K130, 546113L130, 546113L770, 546113K020	HYUNDAI SONATA V (NF) 01/05-> HYUNDAI GRANDEUR (TG) 04/05->
CT342133R	Shock Absorber	520804, 520814, 520819, 520806, 520820	PEUGEOT 308 I (4A_, 4C_) 09/07-> PEUGEOT 308 SW I (4E_, 4H_) 09/07->
HY342056	Shock Absorber	553112S400, 553112Y450, 553112Y900, 553112Y950, 553113U100	HYUNDAI ix35 (LM, EL, ELH) 08/09-> KIA SPORTAGE III (SL) 01/14->
HY342155L	Shock Absorber	546512E500, 546512E201, 546511F000	HYUNDAI TUCSON (JM) 08/04-> KIA SPORTAGE II (JE_, KM_) 09/04->
LA342074	Shock Absorber	21900291540200, 21900291540251, 21900291500400, 21902915402, 21902915004	LADA PRIORA (2170_) 04/07-> LADA SAMARA (2108, 2109, 2113, 2114) 02/09-> LADA GRANTA (2190_) 10/11-> LADA SAMARA (21099, 2115) 01/00->
GM342169	Shock Absorber	13332639, 13412145, 22825519	CHEVROLET CRUZE (J300) 05/09-> OPEL ASTRA J (P10) 12/09-> OPEL ASTRA J 06/12-> CHEVROLET CRUZE (J305) 01/12->
MS342101	Shock Absorber	A2513200730, A251320073064, 2513200730, 251320073064	MERCEDES-BENZ R-CLASS (W251, V251) 07/05->
HY342038	Shock Absorber	553101E200, 553101E100, 553101E000, 55300H8550	HYUNDAI ACCENT III (MC) 11/05->
FR342191R	Shock Absorber	1709762, 1710076, 1851884, 1731866, 1710077	FORD FOCUS III 07/10-> FORD C-MAX II (DXA/CB7, DXA/CEU) 12/10-> FORD GRAND C-MAX (DXA/CB7, DXA/CEU) 12/10->
GM342246L	Shock Absorber	95353836, 95137365, 344913	OPEL MOKKA / MOKKA X (J13) 01/13-> CHEVROLET TRAX 03/13->
WG342066	Shock Absorber	3B5513031B, 3B9513031G, 3B5513031E, 3B0513031P, 3B9513031N	VW PASSAT B5.5 (3B3) 11/00-> VW PASSAT B5 (3B2) 10/96-> AUDI A6 C5 (4B2, 4B4) 02/97-> SKODA SUPERB I (3U4) 12/01->
MZ342217L	Shock Absorber	GS1D34900G, GS1D34900F, GS1D34900E, GS1D34900C, GAM634900A	MAZDA 6 (GH) 08/07->
NS342310R	Shock Absorber	55302EQ025, 553028H327, 553028H326, 553028H625, 55302EQ026	NISSAN X-TRAIL I (T30) 07/01-> KIA CARNIVAL II (GQ) 10/01-> KIA CARNIVAL I (UP, FL) 08/99->
WG342113	Shock Absorber	1K0413031BK, 5C0413031J, 1K0413031BF, 1K0413031CL, 1K0413031BA	SKODA OCTAVIA II (1Z3) 06/04-> VW JETTA IV (162, 163, AV3, AV2) 12/11-> SKODA YETI (5L) 09/09-> VW JETTA III (1K2) 09/04->
TY342494L	Shock Absorber	4852080203, 4852009Y20, 4852080110, 485208Z150, 4852080392	TOYOTA COROLLA (E15_) 10/06-> TOYOTA AURIS (E15_) 02/09->
CT342062	Shock Absorber	9674665480, 9674665580, 9824997280, 3647912	CITROËN C-ELYSEE (DD_) 11/12-> PEUGEOT 301 11/12->

CT342070	Shock Absorber	4162A050, 5206LC, MN101520, 5206LE, 1606293380	CITROËN C3 III (SX) 05/18-> MITSUBISHI OUTLANDER II (CW_W) 09/07-> PEUGEOT 4007 (VU_, VV_) 02/07-> CITROËN C-CROSSER (VU_, VV_) 08/08->
WG342117	Shock Absorber	6R0413031J, 6RF413031B, 6R0413031BA, 6R0413031F, 6RF413031C	VW POLO V (602, 604, 612, 614) 05/10-> VW POLO V (6R1, 6C1) 03/09-> AUDI A1 (8X1, 8XK) 05/10-> AUDI A1 (8XA, 8XF) 11/11->
FR342047	Shock Absorber	1919324, 1681184, BGV428910, 1468811, BEK628910C	FORD FOCUS II (DB_, FCH, DH) 04/05-> FORD FOCUS II (DA_, HCP, DP) 07/04-> MAZDA 3 (BL) 12/08-> VOLVO S40 II (544) 01/04->
HY342181R	Shock Absorber	54661M0000, 54661M0200, 54661M0100, 54661M4000, 54661M4200	HYUNDAI CRETA 01/16->
CT342134L	Shock Absorber	520803, 520805, 1674699180	PEUGEOT 308 I (4A_, 4C_) 09/07-> PEUGEOT 308 SW I (4E_, 4H_) 09/07->
MT342139	Shock Absorber	4060A320, MN101957, MR589639	MITSUBISHI LANCER VII (CS_A, CT_A) 09/03-> MITSUBISHI LANCER VII (CS_W, CT_W) 09/03->
WG342087	Shock Absorber	7H0513029D, 7H0513029E, 7H5513029C, 7E0513029C, 7E0513029D	VW TRANSPORTER T5 (7HA, 7HH, 7EA, 7EH) 04/03-> VW TRANSPORTER T5 (7HB, 7HJ, 7EB, 7EJ) 09/09-> VW TRANSPORTER T6 / CARAVELLE T6 (SGB, SGJ, SHB, SHJ) 04/15-> VW MULTIVAN T5 (7HM, 7HN, 7HF, 7EF, 7EM, 7EN) 09/09->
MS342131	Shock Absorber	A9063200731, A9063200031, 2E0513029AD, 2E0513029, A9063200131	VW CRAFTED 30-50 (2E_) 04/06-> VW CRAFTED 30-35 (2E_) 04/06-> MERCEDES-BENZ SPRINTER 3-t (B906) 06/06-> MERCEDES-BENZ SPRINTER 3,5-t (B906) 06/06->
GM342231R	Shock Absorber	13412719, 13331989, 13331987	CHEVROLET CRUZE (J300) 05/09-> CHEVROLET CRUZE (J305) 01/12-> OPEL AMPERA (R12) 11/11->
DW342037L	Shock Absorber	96980826, 96653293, 96653231	CHEVROLET AVEO / KALOS (T250, T255) 09/08-> ZAZ VIDA (SF6_, SA6_) 01/12-> ZAZ VIDA (SF4_, SA4_) 01/12-> CHEVROLET AVEO / KALOS (T200) 05/03->
GM342212R	Shock Absorber	96407820, 96561721, 96561722	CHEVROLET LACETTI (J200) 03/05-> DAEWOO NUBIRA (J200) 07/03-> DAEWOO LACETTI (KLAN) 02/04-> CHEVROLET NUBIRA 01/06->
HY342083L	Shock Absorber	546501G200, 546501E200, 546501E000, 546500M500, 546501G400	KIA RIO II (JB) 03/05-> HYUNDAI ACCENT III (MC) 11/05->
VL342042L	Shock Absorber	31277201, 31340323, 31329496, 31304051, 31262901	FORD MONDEO IV (BA7) 03/07-> VOLVO XC70 II (136) 08/07-> VOLVO S80 II (124) 01/10-> VOLVO V70 III (135) 08/07->
RN342106	Shock Absorber	543022344R, 6001550751, 543024989R, 8200807029, 6001547071	RENAULT LOGAN I (LS_) 09/04-> RENAULT SANDERO/STEPWAY I (BS_) 02/09->
CT342158R	Shock Absorber	4060A174, 5208S1, 5202ZR, 5202X6, 5202ZQ	MITSUBISHI OUTLANDER II (CW_W) 09/07-> PEUGEOT 4007 (VU_, VV_) 02/07-> CITROËN C-CROSSER (VU_, VV_) 08/08->
HY342150R	Shock Absorber	54660H5100, 54660H0350, 54660H0300, 54660H5150, 54660H0200	HYUNDAI SOLARIS (HCR, HCI) 01/17->
HY342151L	Shock Absorber	54650H5100, 54650H0300, 54650H0350, 54650H5150, 54650H5000	HYUNDAI SOLARIS (HCR, HCI) 01/17->
HY342108R	Shock Absorber	5536117600, 5536117630, 5536117500, 5536117200, 5536117100	HYUNDAI MATRIX (FC) 06/01->
MZ342181R	Shock Absorber	GMM634700, GML834700A, GHP934700B, GHT634700A, GHP934700C	MAZDA 6 (GJ, GL) 12/12->
CT342108L	Shock Absorber	9806013380, 9805824480, 9819233780, 9819219180, 9810768680	CITROËN C-ELYSEE (DD_) 11/12-> PEUGEOT 301 11/12->
SZ342086	Shock Absorber	4180079J02, 4180080J01, 4180080J21, 4180080J20, 4180075K11	SUZUKI SX4 (EY, GY) 06/06->
WG342124	Shock Absorber	1K0413031BK, 5C0413031J, JZW413031H, 1K0413031BF, 1K0413031CL	SKODA OCTAVIA II (1Z3) 06/04-> VW JETTA IV (162, 163, AV3, AV2) 12/11-> SKODA YETI (5L) 09/09-> VW JETTA III (1K2) 09/04->
FR342085	Shock Absorber	1881214, 2068019, 1751388, 1851886, 1751389	FORD FOCUS III 07/10-> VOLVO V40 (525) 03/12-> FORD C-MAX II (DXA/CB7, DXA/CEU) 12/10-> FORD FOCUS II (DB_, FCH, DH) 04/05->
AU342030L	Shock Absorber	4F0616031M, 4F0616031K, 4F0616031A, 4F0616031J, 4F0616031L	AUDI A6 C6 (4F2) 05/04-> AUDI A6 C6 (4F5) 03/05-> AUDI A6 Allroad C6 (4FH) 05/06->
AU342046	Shock Absorber	1J0513025BF, 1J0513025BG, 8N0513025C, 1J0512011AA, 8N0513025J	SKODA OCTAVIA I (1U2) 09/00-> VW GOLF IV (1J1) 10/97-> VW BORA I (1J2) 10/98-> SKODA OCTAVIA I (1U5) 09/00->
AU342057	Shock Absorber	4G5513035, 8K0513035K, 8T0513035L, 8K0513035AK, 8T0513035T	AUDI A6 C7 (4G2, 4GC) 05/11-> AUDI A4 B8 (8K2) 11/11-> AUDI A7 (4GA, 4GF) 10/10-> AUDI A5 (8T3) 05/09->
HY342105L	Shock Absorber	546501G200, 546501E200, 546501E000, 546500M500, 546501G400	KIA RIO II (JB) 03/05->

SHOCK ABSORBER



BW342160R	Shock Absorber	31326764462, 31306775056, 31326764458, 31326764464, 31316766997	HYUNDAI ACCENT III (MC) 11/05-> BMW 5 (E60) 03/05-> BMW 5 (E61) 09/07->
AU342060	Shock Absorber	4G5513035G, 8K0513035BB, 4G5513035E, 8K0513035AF, 4GD513035B	AUDI A6 C7 (4G2, 4GC) 05/11-> AUDI A4 B8 (8K2) 11/11-> AUDI A5 (8T3) 05/09-> AUDI A5 (8TA) 09/09->
AU342066	Shock Absorber	8K0413031BH, 8K0413031AQ, 8K0413031AE, 8K0413031BB, 8K0413031CG	AUDI A4 B8 (8K2) 11/11-> AUDI A4 Allroad B8 (8KH) 04/09-> AUDI A5 (8T3) 05/09-> SEAT ALTEA XL (5P5, 5P8) 05/09->
AU342070	Shock Absorber	8R0413031F, 8T0413031AD, 8R0413031G, 8K0413031CB, 8K0413031CA	AUDI Q5 (8RB) 06/12-> AUDI A5 (8T3) 05/09-> AUDI A5 (8TA) 09/09->
BW342142	Shock Absorber	31326764462, 31306775056, 31326764458, 31326764464, 31316766997	BMW 5 (E60) 03/05-> BMW 5 (E61) 09/07->
GM342313R	Shock Absorber	95948812, 95948816, 4806442	CHEVROLET CAPTIVA (C100, C140) 06/06-> OPEL ANTARA A (L07) 08/06->
AU342090	Shock Absorber	4B0412031M, 3B0413031, 3B0413031A, 8D0413031AC, 8D0413031BF	VW PASSAT B5 (3B2) 10/96-> AUDI A4 B5 (8D2) 11/94-> AUDI A6 C5 (4B2, 4B4) 02/97-> VW PASSAT B5 (3B5) 06/97->
AU342082	Shock Absorber	443413031G, 4A0413031, 4A0413031M, 4A0413031N, 4A0413031D	AUDI 100 C4 (4A2) 12/90-> AUDI 100 C3 (443, 444) 08/82-> AUDI A6 C4 (4A2) 06/94-> AUDI 100 C4 (4A5) 09/91->
AU342081	Shock Absorber	443413031G, 4A0413031, 4A0413031M, 4A0413031N, 4A0413031D	AUDI 100 C4 (4A2) 12/90-> AUDI 100 C3 (443, 444) 08/82-> AUDI A6 C4 (4A2) 06/94-> AUDI 100 C4 (4A5) 09/91->
AU342073	Shock Absorber	8R0413031BE, 8R0413031N, 8R0413031AP, 8R0413031BD, 8F0413031AB	AUDI Q5 (8RB) 06/12-> AUDI A5 (8F7) 10/11->
AU342029R	Shock Absorber	4F0616032M, 4F0616032K, 4F0616032F, 4F0616032L, 4F0616032E	AUDI A6 C6 (4F2) 05/04-> AUDI A6 C6 (4F5) 03/05-> AUDI A6 Allroad C6 (4FH) 05/06->
DW342035L	Shock Absorber	96424401, 96424025	CHEVROLET SPARK 05/05-> CHEVROLET MATIZ (M200, M250) 03/05->
CR342051	Shock Absorber	4060A045, MN101532, MN101644, MN100388, MN184208	MITSUBISHI OUTLANDER II (CW_W) 09/07-> MITSUBISHI OUTLANDER I (CU_W) 11/03-> PEUGEOT 4007 (VU_, VV_) 02/07-> CITROËN C-CROSSER (VU_, VV_) 08/08->
HY342167R	Shock Absorber	546602B200, 546602B201, 546502B000, 546602B001	HYUNDAI SANTA FÉ II (CM) 07/10->
RN342071	Shock Absorber	562100664R, 562100325R, 8660004148	RENAULT FLUENCE (L3_) 02/10->
HY342201R	Shock Absorber	546613Z320, 546613Z920, 546613Z120, 546613Z700, 546613Z110	HYUNDAI i40 I (VF) 10/12-> HYUNDAI i40 I CW (VF) 10/12->
MS342121	Shock Absorber	A6383260700, A6383261200, A6383261100, 6383260700, A6383260800	MERCEDES-BENZ VITO (W638) 03/99-> MERCEDES-BENZ V-CLASS (638/2) 03/99->
MT342110	Shock Absorber	4162A364, 4162A110, 4162A413, 4162A335, NSFKG40RT	MITSUBISHI PAJERO SPORT II (KH_, KG_) 07/08-> MITSUBISHI PAJERO SPORT III (KS_) 08/15->
MT342164R	Shock Absorber	4060A464, 4060A474, 4060A050, 4060A326	MITSUBISHI OUTLANDER II (CW_W) 09/07-> PEUGEOT 4007 (VU_, VV_) 02/07-> CITROËN C-CROSSER (VU_, VV_) 08/08->
MT342165L	Shock Absorber	4060A463, 4060A049, 4060A473, 4060A325	MITSUBISHI OUTLANDER II (CW_W) 09/07-> PEUGEOT 4007 (VU_, VV_) 02/07-> CITROËN C-CROSSER (VU_, VV_) 08/08->
MT342198	Shock Absorber	4162A036, 4162A175	MITSUBISHI LANCER VIII (CY_A, CZ_A) 06/08-> MITSUBISHI LANCER VIII (CX_A) 06/08->
TY342489L	Shock Absorber	4854039755, 4854080015, 4854080022, 4854080010, 4854009660	TOYOTA CAMRY (V4_) 01/06->
RN342133	Shock Absorber	543022344R, 6001550751, 5611000Q0B, 543024989R, 5611000Q0A	RENAULT LOGAN I (LS_) 09/04-> LADA LARGUS (KS0_, RS0_, KSA_) 09/17-> RENAULT SANDERO/STEPWAY I (BS_) 02/09-> RENAULT LOGAN I (KS_) 04/07->
RN342146	Shock Absorber	543023532R, 543020017R, 543022646R, 8660004188, 543023826R	RENAULT SCÉNIC III (JZ0/1_) 04/09-> RENAULT GRAND SCÉNIC III (JZ0/1_) 04/09->
WG342060	Shock Absorber	3BD513031, 4B0513031J, 4B0513031T, 8D0413031AG, 8D0413031BC	VW PASSAT B5.5 (3B3) 11/00-> VW PASSAT B5 (3B2) 10/96-> AUDI A6 C5 (4B2, 4B4) 02/97-> SKODA SUPERB I (3U4) 12/01->
MS342035	Shock Absorber	A1643203031, A1643200731, A1643202731, A1643202031, A1643201131	MERCEDES-BENZ M-CLASS (W164) 02/05-> MERCEDES-BENZ GL-CLASS (X164) 09/06->
MT342207	Shock Absorber	4162A130, 4162A245, 4162A304, 4162A239, 4162A034	MITSUBISHI ASX (GA_W_) 06/10-> PEUGEOT 4008 05/12-> CITROËN C4 AIRCROSS 04/12->
LA342019R	Shock Absorber	21700290540203, 21700290500200, 21702905002,	LADA PRIORA (2170_) 04/07->

		21700290540200, 21700290540250	LADA PRIORA (2172) 12/08-> LADA 112 (2112) 03/06-> LADA 110 (2110) 01/00->
AU342058	Shock Absorber	8R0513035E, 8R0513035R, 8R0513035J, 8R0513035AE, 8R0513035C	AUDI Q5 (8RB) 06/12->
KI342134L	Shock Absorber	546303E100, 546303E300, 546303E200, 536303E200	KIA SORENTO I (JC) 12/06->
KI342133R	Shock Absorber	546403E300, 546403E100, 546403E200, 536403E200	KIA SORENTO I (JC) 12/06->
HY342080R	Shock Absorber	5466007100, 546600X100, 5466007200, 546600X200	KIA PICANTO I (SA) 04/04-> HYUNDAI i10 I (PA) 01/08->
GM342229L	Shock Absorber	93195924, 344670, 344154	OPEL ZAFIRA / ZAFIRA FAMILY B (A05) 07/05-> OPEL ASTRA H (A04) 09/08-> OPEL ASTRA H GTC (A04) 01/06-> OPEL ASTRA H CLASSIC (A04) 01/09->
BW342037L	Shock Absorber	37116793865, 37106866515, 37116874517, 37116864751, 37106865567	BMW 3 (F30, F80) 07/12-> BMW 1 (F20) 07/11-> BMW 1 (F21) 12/11-> BMW 3 (F34) 07/15->
BW342036R	Shock Absorber	37116793866, 37116874518, 37106866516, 37116864752, 37116865540	BMW 3 (F30, F80) 07/12-> BMW 1 (F20) 07/11-> BMW 1 (F21) 12/11-> BMW 3 (F34) 07/15->
BW342029L	Shock Absorber	37106875087, 37126863175, 6875087, 6867867, 6863175	BMW X6 (F16, F86) 12/14-> BMW X5 (F15, F85) 12/13->
BW342028R	Shock Absorber	37106875088, 37126863176, 6867868, 37106867868, 6875088	BMW X6 (F16, F86) 12/14-> BMW X5 (F15, F85) 12/13->
WG342093	Shock Absorber	2K0513029M, 2K5513029G, 2K0513029F, 2K5513029E, 2K03513029F	VW CADDY III (2KB, 2KJ, 2CB, 2CJ) 04/04-> VW CADDY IV (SAB, SAJ) 11/15-> VW CADDY ALLTRACK IV (SAB) 11/15->
LA342014L	Shock Absorber	21100290540303, 21102905003, 21100290500302, 21100290540330, 21100290540340	LADA 110 (2110) 01/95-> LADA 112 (2112) 03/06-> LADA 111 (2111) 01/96->
WG342118	Shock Absorber	1K0413031BK, 5C0413031J, 1K0413031BF, 1K0413031CL, 1K0413031BA	VW CADDY III (2KB, 2KJ, 2CB, 2CJ) 04/04->
FR342126R	Shock Absorber	1329533, 1329534, 274215, D35034700C, 1349766	FORD FUSION (JU_) 08/02-> FORD FIESTA V (JH_, JD_) 11/01-> MAZDA 2 (DY) 04/03->
FR342127L	Shock Absorber	1329536, 2S6118146BA, 1436173, 1354941, 1350286	FORD FUSION (JU_) 08/02-> FORD FIESTA V (JH_, JD_) 11/01-> MAZDA 2 (DY) 04/03->
HY342055	Shock Absorber	553112Y350, 553113U000, 553113V010, 553114C120, 553112T120	KIA SPORTAGE III (SL) 06/10-> HYUNDAI ix35 (LM, EL, ELH) 08/09-> HYUNDAI i40 I (VF) 10/12-> HYUNDAI SONATA VI (YF) 06/09->
HY342081L	Shock Absorber	5465007100, 546500X100, 546500X200	KIA PICANTO I (SA) 04/04-> HYUNDAI i10 I (PA) 01/08->
KI342106R	Shock Absorber	546611H001, 546611H000, 546611H100, 546611H101	KIA CEE'D (ED) 12/06-> KIA CEE'D SW (ED) 09/07-> KIA PRO CEE'D (ED) 01/09->
KI342107L	Shock Absorber	546511H001, 546511H000, 546511H100, 546511H101	KIA CEE'D (ED) 12/06-> KIA CEE'D SW (ED) 09/07-> KIA PRO CEE'D (ED) 10/10->
LA342008	Shock Absorber	21230291540203, 21214291540200, 21232915004, 21214291500400, 21212915402	CHEVROLET NIVA (2123) 01/10-> LADA NIVA (2121, 2131) 05/04->
LA342013R	Shock Absorber	21100290540203, 21102905002, 21100290500202, 21100290540240, 21100290540230	LADA 110 (2110) 01/95-> LADA 112 (2112) 03/06-> LADA 111 (2111) 01/96->
LA342020L	Shock Absorber	21700290540303, 21700290500300, 21700290540300, 21700290540350, 11192905003	LADA PRIORA (2170_) 04/07-> LADA PRIORA (2172) 12/08-> LADA 112 (2112) 03/06-> LADA 110 (2110) 01/00->
LA342076R	Shock Absorber	21900290540200, 21900290540251, 21900290500200, 21902905002, 543025PA1C	LADA GRANTA (2190_) 10/11-> LADA GRANTA (2191_) 08/14->
LA342075L	Shock Absorber	21900290540300, 21900290540351, 21900290500300, 21902905003	LADA GRANTA (2190_) 10/11-> LADA GRANTA (2191_) 08/14->
MS342129	Shock Absorber	A2043260500, A2383207301, A2053207330, A2043260200, A2053208730	MERCEDES-BENZ E-CLASS (W212) 01/13-> MERCEDES-BENZ C-CLASS (W204) 01/07-> MERCEDES-BENZ C-CLASS (W205) 10/18-> MERCEDES-BENZ E-CLASS (C207) 06/13->
GM342228R	Shock Absorber	344671, 344357, 344155	OPEL ZAFIRA / ZAFIRA FAMILY B (A05) 07/05-> OPEL ASTRA H (A04) 09/08-> OPEL ASTRA H GTC (A04) 01/06-> OPEL ASTRA H CLASSIC (A04) 01/09->
TY342488R	Shock Absorber	4853089025, 4853080619, 4853080727, 4853080527, 4853009K70	TOYOTA CAMRY (_V4_) 01/06->
HY342112R	Shock Absorber	546612H000, 546612H100	HYUNDAI ELANTRA IV (HD) 06/06->
HY342113L	Shock Absorber	546512H000, 546512H100	HYUNDAI ELANTRA IV (HD) 06/06->
HY342193R	Shock Absorber	54661A2500, 54661A2205, 54661A2255, 54661A2550, 54661A6500	HYUNDAI i30 (GD) 12/11->

SHOCK ABSORBER



			KIA CEE'D (JD) 05/12-> HYUNDAI i30 05/13-> KIA PRO CEE'D (JD) 07/15->
HY342194L	Shock Absorber	54651A2500, 54651A2255, 54651A6500, 54651A2550, 54651A6510	HYUNDAI i30 (GD) 12/11-> KIA CEE'D (JD) 05/12-> HYUNDAI i30 05/13-> KIA PRO CEE'D (JD) 03/13->
WG342074	Shock Absorber	5Q0513029JE, 3Q0513049GQ, 3Q0513049FT, 3Q0513049GF, 5Q0513029EM	SKODA OCTAVIA III (5E3, NL3, NR3) 01/14-> VW TIGUAN (AD1, AX1) 05/16-> SKODA KODIAQ I (NS6, NS7, NV7) 10/16-> VW GOLF VII (5G1, BQ1, BE1, BE2) 11/12->
HY342066	Shock Absorber	553113K130, 553113K770, 553113L130, 553113L770, 553113K780	HYUNDAI SONATA V (NF) 01/05-> HYUNDAI GRANDEUR (TG) 04/05->
HY342215	Shock Absorber	546113D601, 5461138701, 546113D600, 5461138601, 5461138500	HYUNDAI SONATA IV (EF) 10/01-> KIA MAGENTIS I (GD, MS) 05/01-> HYUNDAI XG (XG) 12/98-> HYUNDAI XG 10/03->
WG342091	Shock Absorber	1K0513029MP, 1K0513029MQ, 5C0513029D, 1K0513029ME, 3AA513049B	SKODA OCTAVIA II (1Z3) 06/04-> VW JETTA IV (162, 163, AV3, AV2) 12/11-> SKODA YETI (5L) 09/09-> VW PASSAT B7 (362) 02/11->
NS342313L	Shock Absorber	54303EQ025, 543038H726, 543038H725, 543038H625, 543038H700	NISSAN X-TRAIL I (T30) 07/01->
TY342403R	Shock Absorber	4851080309, 4851080312, 4851080486, 4851009M90, 4851080308	TOYOTA CAMRY (V4_) 01/06-> LEXUS ES (V4_) 05/06->
HY342223	Shock Absorber	55300A2500, 55300A6700, 55300A2520, 55300A2510, 55300A6500	KIA CEE'D (ED) 12/06-> KIA CEE'D SW (ED) 09/07-> HYUNDAI i30 (GD) 12/11-> HYUNDAI i30 (FD) 02/08->
NS342312R	Shock Absorber	54302EQ025, 543028H726, 543028H725, 54302EQ026, 543028H625	NISSAN X-TRAIL I (T30) 07/01->
WG342108	Shock Absorber	1J0413031AM, 1J0413031S, 1J0413031BH, 1J0413031AE, 1J0413031N	SKODA OCTAVIA I (1U2) 09/00-> VW GOLF IV (1J1) 10/97-> VW BORA I (1J2) 10/98-> SKODA OCTAVIA I (1U5) 09/00->
HY342076R	Shock Absorber	5536025101, 5536025151, 5536025150, 5536025050, 5536025051	HYUNDAI ACCENT II (LC) 09/99-> HYUNDAI ACCENT (X-3) 10/94-> HYUNDAI ACCENT I (X-3) 10/94->
KI342052L	Shock Absorber	5465025150, 5465025100, 5465025050, 5465025750, 5465025000	HYUNDAI ACCENT II (LC) 09/99-> HYUNDAI ACCENT I (X-3) 10/94->
KI342051R	Shock Absorber	5466025150, 5466025100, 5466025050, 5466025750, 5466025000	HYUNDAI ACCENT II (LC) 09/99-> HYUNDAI ACCENT I (X-3) 10/94->
TY342522L	Shock Absorber	4852080281, 4852080396, 4852080282, 4852080398, 4852009V80	TOYOTA CAMRY (V5_) 09/11->
WG342123	Shock Absorber	5Q0413023FR, 5Q0413023FH, 5Q0413023FJ, 5Q0413023EB, 5Q0413023FQ	SKODA OCTAVIA III (5E3, NL3, NR3) 01/14-> VW GOLF VII (5G1, BQ1, BE1, BE2) 11/12-> AUDI A3 (8VS, 8VM) 05/14-> AUDI A3 (8V1, 8VK) 04/12->
WG342135	Shock Absorber	5C0413031BQ, 1T0413031DC, 8J0413031T, 1T0413031BH, 824904003291	VW TIGUAN (5N_) 09/07-> SKODA YETI (5L) 09/09-> AUDI TT (8J3) 06/08-> AUDI TT (8J9) 06/08->
TY342404L	Shock Absorber	4852080090, 4852080093, 4852080226, 4852009F40, 4852080089	TOYOTA CAMRY (V4_) 01/06-> LEXUS ES (V4_) 05/06->
TY342306	Shock Absorber	4853006A50, 4853006A51, 4853080810, 485308Z105, 4853080812	TOYOTA CAMRY (V7_, _VA7_, _VH7_) 08/17->
WG342139	Shock Absorber	5Q0413031ER, 5Q0413031FP, 3Q0413031CT, 5Q0413031EL, 8V0413031AC	SKODA OCTAVIA III (5E3, NL3, NR3) 01/14-> VW TIGUAN (AD1, AX1) 05/16-> SKODA KODIAQ I (NS6, NS7, NV7) 10/16-> VW GOLF VII (5G1, BQ1, BE1, BE2) 11/12->
TY342601R	Shock Absorber	4853089025, 4853080527, 4853009K70, 4853009N60, 4853009M20	LEXUS ES (V4_) 05/06->
TY342619L	Shock Absorber	485208Z307, 4852080536, 485208Z192, 485208Z181, 485208Z190	TOYOTA CAMRY (V7_, _VA7_, _VH7_) 08/17->
HY342077L	Shock Absorber	5535025150, 5535025151, 5535025101, 5535025050, 5535025100	HYUNDAI ACCENT II (LC) 09/99-> HYUNDAI ACCENT (X-3) 10/94-> HYUNDAI ACCENT I (X-3) 10/94->
TY342521R	Shock Absorber	4851080559, 4851080702, 4851080560, 4851080704, 4851080627	TOYOTA CAMRY (V5_) 09/11->
TY342602L	Shock Absorber	4854039755, 4854080010, 4854009660, 4854009810, 4854039785	LEXUS ES (V4_) 05/06->
TY342618R	Shock Absorber	485108Z460, 4851080863, 485108Z334, 485108Z321, 4851080861	TOYOTA CAMRY (V7_, _VA7_, _VH7_) 08/17->
BW342183	Shock Absorber	33521093646, 1093646, 33521094467, 1094467	BMW 5 (E39) 09/95->
BW342158L	Shock Absorber	31311096858, 31311096862, 31311093644, 1096858, 1096862	BMW 5 (E39) 09/95->
BW342157R	Shock Absorber	31311096858, 31311096862, 31311093644, 1096858, 1096862	BMW 5 (E39) 09/95->
BW342133	Shock Absorber	31316874367, 31316873721, 31316873797, 31316873723, 31316873762	BMW 3 (F30, F80) 07/12-> BMW 1 (F20) 07/11-> BMW 1 (F21) 12/11-> BMW 3 (F34) 07/15->
BW342092L	Shock Absorber	31316786017, 31316796155, 31316786005, 31316786021, 31316786001	BMW 3 (E90) 09/07-> BMW 1 (E81) 09/07-> BMW 1 (E87) 06/04->

SHOCK ABSORBER



BW342091R	Shock Absorber	31316786018, 31316796156, 31316786002, 31316786006, 31316786022	BMW 1 (E82) 09/09-> BMW 3 (E90) 09/07-> BMW 1 (E87) 06/04-> BMW 1 (E81) 09/07-> BMW 1 (E82) 09/09->
HY342157L	Shock Absorber	553512E501, 553510Z001, 553502E500, 553510Z000, 553512E202	HYUNDAI TUCSON (JM) 08/04-> KIA SPORTAGE II (JE_, KM_) 09/04->
HY342156R	Shock Absorber	553612E501, 553602E500, 553610Z001, 553610Z000, 553612E202	HYUNDAI TUCSON (JM) 08/04-> KIA SPORTAGE II (JE_, KM_) 09/04->
HY342068	Shock Absorber	55311D7120, 55311F1530, 55311D7000, 55311D7510, 55311F1520	HYUNDAI TUCSON (TL, TLE) 06/15-> KIA SPORTAGE IV (QL, QLE) 09/15->
HY342169R	Shock Absorber	546612S000, 546612Y360, 546612Y610, 546613U000, 546612Y500	KIA SPORTAGE III (SL) 06/10-> HYUNDAI ix35 (LM, EL, ELH) 08/09->
HY342170L	Shock Absorber	546512S000, 546513U000, 546512Y610, 546512Y360, 546512Y500	KIA SPORTAGE III (SL) 06/10-> HYUNDAI ix35 (LM, EL, ELH) 08/09->
GM342337	Shock Absorber	96445038, 96226992	DAEWOO NEXIA 02/95-> DAEWOO LANOS (KLAT) 05/97-> DAEWOO ESPERO (KLEJ) 02/95-> OPEL KADETT E (T85) 09/85->
WG342062	Shock Absorber	6Q0513025AH, 6R0513025AR, 1J0513025BL, 1J0513025DG, 1J0513025BH	SKODA FABIA II (542) 01/07-> SKODA OCTAVIA I (1U2) 09/00-> VW GOLF IV (1J1) 10/97-> VW POLO V (6R1, 6C1) 03/09->
AU342089	Shock Absorber	4F0413031AQ, 4F0413031AR, 4F0413031AS, 4F0413031AL, 4F0413031AB	AUDI A6 C6 (4F2) 05/04-> AUDI A6 C6 (4F5) 03/05->
WG342073	Shock Absorber	3BD513031, 4B0513031J, 4B0513031T, 8D0413031AG, 8D0413031BC	VW PASSAT B5.5 (3B3) 11/00-> VW PASSAT B5 (3B2) 10/96-> AUDI A6 C5 (4B2, 4B4) 02/97-> SKODA SUPERB I (3U4) 12/01->
WG342077	Shock Absorber	5Q0513049HQ, 5Q0513049FC, 5Q0513049DL, 5Q0513049DG, 5QM513049AA	SKODA OCTAVIA III (5E3, NL3, NR3) 01/14-> VW GOLF VII (5G1, BQ1, BE1, BE2) 11/12-> AUDI A3 (8VS, 8VM) 05/14-> AUDI A3 (8V1, 8VK) 04/12->
KI342027	Shock Absorber	55310H5050, 55310H5000, 553101G210, 553101G220, 55310H0000	HYUNDAI SOLARIS (HCR, HCI) 01/17-> KIA RIO IV (SC, FB) 07/17-> KIA RIO II (JB) 03/05-> KIA STONIC (YB) 11/18->
FR342152R	Shock Absorber	1595291, 1570032, 1681181, 1681179, 1360156	FORD FOCUS II (DB_, FCH, DH) 04/05-> FORD FOCUS II (DA_, HCP, DP) 07/04-> FORD FOCUS II (DA_, FFS, DS) 07/04-> FORD FOCUS C-MAX (DM2) 03/04->
FR342153L	Shock Absorber	1595298, 1619269, 1619274, 1681187, 1681215	FORD FOCUS II (DB_, FCH, DH) 04/05-> FORD FOCUS II (DA_, HCP, DP) 07/04-> FORD FOCUS II (DA_, FFS, DS) 07/04-> FORD FOCUS C-MAX (DM2) 03/04->
GM342186L	Shock Absorber	96407821, 96955950	CHEVROLET LACETTI (J200) 03/05-> DAEWOO LACETTI (KLAN) 02/04-> CHEVROLET NUBIRA 03/05->
GM342185R	Shock Absorber	96407822, 96955951	CHEVROLET LACETTI (J200) 03/05-> CHEVROLET NUBIRA 03/05-> DAEWOO LACETTI (KLAN) 02/04->
RN342123	Shock Absorber	543027341R, 543027096R, 543025333R, 543020986R, 543020952R	RENAULT LOGAN/STEPWAY II (L8_) 04/14->
WG342130	Shock Absorber	JZW413031A, 1T0413031HQ, 3AA413031N, 3C0413031AJ, JZW498031A	VW JETTA IV (162, 163, AV3, AV2) 12/11-> VW TIGUAN (5N_) 09/07-> VW PASSAT B7 (362) 02/11-> VW GOLF V (1K1) 01/04->
KI342132	Shock Absorber	553111H500, 553101H000, 553101H201, 553101H100, 553101H001	KIA CEE'D (ED) 12/06-> KIA CEE'D SW (ED) 09/07-> KIA PRO CEE'D (ED) 02/08->
NS342376R	Shock Absorber	E43024EA8C, E43024EA6B, 54302HV01A, 543024EA7C, 543024EA3A	NISSAN QASHQAI II (J11, J11_) 12/13->
NS342377L	Shock Absorber	E43034EA8C, E43034EA6B, 543034EA3A, 543034EA7C, E4303HV01A	NISSAN QASHQAI II (J11, J11_) 12/13->
FR342161R	Shock Absorber	1709762, 1710076, 1851884, 1731866, 1710077	FORD FOCUS III 07/10-> FORD C-MAX II (DXA/CB7, DXA/CEU) 12/10-> FORD GRAND C-MAX (DXA/CB7, DXA/CEU) 12/10->
FR342162L	Shock Absorber	1709759, 1710069, 1851890, 1704766, 1731863	FORD FOCUS III 07/10-> FORD C-MAX II (DXA/CB7, DXA/CEU) 12/10-> FORD GRAND C-MAX (DXA/CB7, DXA/CEU) 02/11->
HN342210	Shock Absorber	52611TL1E01, 52611T2AA13, 52611TA0A03, 52611TL0F01, 52611TL4E01	HONDA ACCORD VIII (CU) 07/08->
GM342152	Shock Absorber	93178641, 93191129, 436334, 93178642	OPEL ASTRA H (A04) 09/08-> OPEL ASTRA H GTC (A04) 01/06-> OPEL ASTRA H CLASSIC (A04) 01/09->
MS342193	Shock Absorber	A2043233000, A2043233600, A2043200630, A2043200530, A2043232700	MERCEDES-BENZ C-CLASS (W204) 01/07-> MERCEDES-BENZ C-CLASS (S204) 08/07->
TY342630R	Shock Absorber	485108Z390, 485108Z427, 4851080A75, 4851080A74, 485108Z429	TOYOTA RAV 4 V (_A5_, _H5_) 12/18->

SHOCK ABSORBER

KI342056L	Shock Absorber	0K2ND34900, 0K2SB34900, 0K2NF34900A, 0K2ND34900A, 0K2NF34900	SUZUKI ACROSS (A5Z_) 06/20-> KIA SHUMA II (FB) 05/01-> KIA CERATO I (LD) 05/06->
BW342065	Shock Absorber	33526874369, 33526873807, 33526874377, 33526873722, 33526873775	BMW 3 (F34) 07/15-> BMW 4 (F32, F82) 03/15-> BMW 3 (F31) 07/15-> BMW 1 (F20) 11/12->
BW342072	Shock Absorber	33506886761, 33506886760, 33506886762, 33526870081, 33506887336	BMW X1 (F48) 11/14-> MINI MINI COUNTRYMAN (F60) 10/16-> BMW X2 (F39) 03/18-> BMW 2 Active Tourer (F45) 07/14->
CT342164L	Shock Absorber	5202ZS, 5208C9, 5208C8, 5208A0, 5202ZV	CITROËN C4 GRAND PICASSO I (UA_) 10/06-> CITROËN C4 PICASSO I (UD_) 07/08-> PEUGEOT 308 CC (4B_) 06/09-> PEUGEOT 308 SW I (4E_, 4H_) 09/07->
HN342182	Shock Absorber	52611SWAA11, 52611SWAE02, 52611S9AA12, 52611S9AG02, 52611S9AA03	HONDA CR-V II (RD_) 09/01->
CT342167R	Shock Absorber	5202WN, 5202EC, 5202CZ, 5208E3, 5202QH	PEUGEOT 307 (3A/C) 08/00-> CITROËN C4 (LA_) 11/04-> CITROËN C4 I (LC_) 11/04-> PEUGEOT 307 SW (3H) 03/02->
HY342054	Shock Absorber	553102B510, 553102P650, 553102B211, 553102P600, 553102P200	KIA SORENTO II (XM) 11/09-> HYUNDAI SANTA FÉ II (CM) 07/10->
VL342034	Shock Absorber	30683451, 31329768, 31329767, 30635776, 31201452	VOLVO XC90 I (275) 10/02->
WG342127	Shock Absorber	8N0413031H, 1J0413031CM, 8N0413031M, 1J0413031BF, 8N0413031R	SKODA OCTAVIA I (1U5) 09/00-> VW GOLF IV (1J5) 05/99-> SKODA ROOMSTER (5J7) 03/06-> VW BORA (1J6) 05/99->
GM342357R	Shock Absorber	344698, 344949, 344700	OPEL ASTRA J (P10) 12/09-> OPEL ASTRA J 06/12-> OPEL ZAFIRA TOURER C (P12) 10/11-> VAUXHALL ZAFIRA TOURER Mk III (P12) 07/13->
RN342075	Shock Absorber	562102480R, 562107788R, 562104719R, 562106372R	RENAULT SANDERO/STEPWAY II (B8_) 04/14->
HY342233	Shock Absorber	55300A7200, 553003X100, 553003X110, 553003X210, 55300A7100	KIA RIO III (UB) 06/11-> HYUNDAI ELANTRA V (MD, UD) 06/11-> HYUNDAI VELOSTER (FS) 04/11->
RN342171	Shock Absorber	8200663654, 8200222460, 2200222457, 8200335195	RENAULT MEGANE II (LM0/1_) 09/03-> RENAULT MEGANE II (BM0/1_, CM0/1_) 11/02-> RENAULT MEGANE II (KM0/1_) 01/07->
BW342217L	Shock Absorber	31316796315, 31316796409, 31316796418, 6796315, 6796409	BMW X3 (F25) 09/10-> BMW X4 (F26) 04/14->
FR342104	Shock Absorber	1933016, 1933017, 1935746, 2001566, 1772583	FORD TRANSIT V363 (FCD, FDD) 08/13-> FORD TRANSIT V363 (FAD, FBD) 08/13-> FORD TOURNEO CUSTOM V362 (F3) 09/12-> FORD TRANSIT CUSTOM V362 (F3) 09/12->
GM342283R	Shock Absorber	95917155, 95465741, 95226438	CHEVROLET AVEO (T300) 03/11->
GM342284L	Shock Absorber	95917154, 95465740, 95917152	CHEVROLET AVEO (T300) 03/11->
TY342631L	Shock Absorber	485208Z242, 4852080699, 4852080634, 485208Z281, 4852080635	TOYOTA RAV 4 V (A5_, H5_) 12/18-> SUZUKI ACROSS (A5Z_) 06/20->
GM342359L	Shock Absorber	344948, 344699, 13412603	OPEL ASTRA J (P10) 12/09-> OPEL ASTRA J 06/12-> OPEL ZAFIRA TOURER C (P12) 10/11-> VAUXHALL ZAFIRA TOURER Mk III (P12) 07/13->
KI342045	Shock Absorber	553001M300, 553001M000, 553001M360, 553001M510, 553001M570	KIA CERATO II (TD) 01/10->
KI342143	Shock Absorber	55300A7200, 553003X100, 553003X110, 553003X210, 55300A7100	HYUNDAI VELOSTER (FS) 04/11->
VL342061R	Shock Absorber	31429129, 31277200, 31340322, 31329495, 31262895	VOLVO XC70 II (136) 08/07-> VOLVO S60 II (134) 05/12-> VOLVO V60 I (155) 03/15-> VOLVO V60 II (225) 02/18->
WG342165	Shock Absorber	4B0412031CE, 4B0412031BQ, 4B0412031BC, 4B0412031AP, 4B0412031CF	VW PASSAT B5.5 (3B3) 11/00-> VW PASSAT B5 (3B2) 10/96-> AUDI A6 C5 (4B2, 4B4) 02/97-> SKODA SUPERB I (3U4) 12/01->
TY342301	Shock Absorber	485310E120, 4853148321, 4853148133, 485310E020, 4853148130	LEXUS RX (L1_) 12/08->
VL342062L	Shock Absorber	31277201, 31429130, 31340323, 31329496, 31304051	VOLVO XC70 II (136) 08/07-> VOLVO S60 II (134) 05/12-> VOLVO V60 I (155) 03/15-> VOLVO V60 II (225) 02/18->
MS342094	Shock Absorber	A2053202330, A2053200130, A2053209230, A2053208330, 2053209230	MERCEDES-BENZ C-CLASS (W205) 10/18-> MERCEDES-BENZ C-CLASS (C205) 10/15-> MERCEDES-BENZ C-CLASS (S205) 06/18-> MERCEDES-BENZ C-CLASS (A205) 06/16->
BW342214L	Shock Absorber	37106869023, 37106896441, 37106869025, 6869023, 6896441	BMW X5 (G05, F95) 08/18-> BMW X6 (G06, F96) 08/19->
FR342062	Shock Absorber	1575022, 1810120, 1866919, 2005873, 1851887	FORD FOCUS III 07/10->

SHOCK ABSORBER



VL342031	Shock Absorber	31340696, 31340694, 30714221, 31304174, 31340700	FORD FOCUS II (DA_, FFS, DS) 07/04-> VOLVO S80 II (124) 01/10-> VOLVO S60 II (134) 05/12-> VOLVO V60 I (155) 03/15-> VOLVO V70 III (135) 08/07->
WG342167	Shock Absorber	7L6513029E, 7L6513029N	VW TOUAREG (7LA, 7L6, 7L7) 01/03->
MS342197	Shock Absorber	A2113231500, A2113239100, A2113231100, A2113232400, A2113239200	MERCEDES-BENZ E-CLASS (W211) 03/02-> MERCEDES-BENZ E-CLASS (S211) 04/06->
BW342222	Shock Absorber	33526866615, 33526866617, 33526896015, 6866617, 6875620	BMW 5 (G30, F90) 09/16->
CT342168L	Shock Absorber	5202WL, 5202EA, 5202CY, 5208E2, 5202QG	PEUGEOT 307 (3A/C) 08/00-> CITROËN C4 (LA_) 11/04-> CITROËN C4 I (LC_) 11/04-> PEUGEOT 307 SW (3H) 03/02->
FR342227L	Shock Absorber	2318381, 2318362, BV6Z18124H, 1934863, 2317523	FORD FOCUS III 07/10-> FORD C-MAX II (DXA/CB7, DXA/CEU) 12/10->
GM342195L	Shock Absorber	93188949, 344654, 0344654	OPEL CORSA D (S07) 07/06-> OPEL ADAM (M13) 10/12-> OPEL CORSA E (X15) 09/14->
TY342332	Shock Absorber	4853069526, 4853069645, 4853069525, 4853080703, 4853069655	TOYOTA LAND CRUISER PRADO (J15_) 08/09-> TOYOTA FJ CRUISER (GSJ1_) 06/05->
TY342610L	Shock Absorber	4852059505, 4852059525, 5208A2, 4852080213, 4852080096	TOYOTA RAV 4 III (A3_) 02/06->
VL342030	Shock Absorber	31262151, 31323227, 31340539, 31340702, 31340703	VOLVO XC70 II (136) 08/07-> VOLVO S80 II (124) 01/10->
HY342073	Shock Absorber	553112S000, 553112T020, 553112Y800, 553113Z510, 553112T010	HYUNDAI i40 I (VF) 10/12-> HYUNDAI SONATA VI (YF) 06/09-> HYUNDAI i40 I CW (VF) 10/12-> KIA OPTIMA (FSGDS6B) 12/12->
WG342175	Shock Absorber	6Q0513025R, 6Q0513025P, JZW513025E, 6Q0513025BN, 6R0513025	SKODA FABIA II (542) 01/07-> VW POLO V (6R1, 6C1) 03/09-> SKODA FABIA I (6Y2) 01/03-> SKODA FABIA II (545) 10/07->
HN342110R	Shock Absorber	51605SMGE06, 51601SMGE19, 51605SMGB01, 51601SMGE18, 51605SMGE04	HONDA CIVIC VIII (FN, FK) 09/05->
NS342354R	Shock Absorber	E4302BA61A, E43021KA1A, E43021KC2B, E43021KC2A, E4302BX81A	NISSAN JUKE (F15) 06/10->
HY342187R	Shock Absorber	54660F1530, 54660F1000, 54660D7000, 54660F1030, 54660D7500	KIA SPORTAGE IV (QL, QLE) 12/15-> HYUNDAI TUCSON (TL, TLE) 06/15->
HY342236	Shock Absorber	553004H000, 553004H100, 553004H050, 553004H150	HYUNDAI H-1 Cargo (TQ) 08/09-> HYUNDAI H-1 Travel (TQ) 05/08->
RN342168	Shock Absorber	543026656R, 543028126R, 543020485R, 543029903R, 543025648R	RENAULT DUSTER (HS_) 02/12-> RENAULT KAPTUR (H5_) 03/16-> RENAULT DUSTER (HM_) 01/18->
SZ342167L	Shock Absorber	4160279JA2, 71746772, 71747482, 71747480, 71746770	SUZUKI SX4 (EY, GY) 07/09-> FIAT SEDICI (189_) 06/06->
CT342091	Shock Absorber	5206RN, 5206RP	PEUGEOT PARTNER TEPEE 04/08-> CITROËN BERLINGO MULTISPACE (B9) 04/08->
FR342076	Shock Absorber	1721245, 1746172, 1746169, 1736049, 1720986	FORD MONDEO IV (BA7) 03/07-> FORD S-MAX (WA6) 05/06-> FORD GALAXY II (WA6) 05/06->
FR342228R	Shock Absorber	2318353, 2318375, BV6Z18124E, FV6Z18124C, 2317501	FORD FOCUS III 07/10-> FORD C-MAX II (DXA/CB7, DXA/CEU) 12/10->
TY342757L	Shock Absorber	4852080497, 4852080349, 4852080316, 4852080413, 4852079295	TOYOTA RAV 4 IV (A4_) 12/12-> LEXUS NX (Z1_) 11/14->
WG342146	Shock Absorber	357513031, 357513031S, 357513033F, 333513031A, 357513031A	VW PASSAT B3/B4 (3A2, 35I) 02/88-> VW PASSAT B3/B4 (3A5, 35I) 02/88->
MS342114	Shock Absorber	A1243200713, A1243202031, A1243262800, A1243262000, A1243205013	MERCEDES-BENZ E-CLASS (W124) 06/93-> MERCEDES-BENZ CЕДАН (W124) 09/85-> MERCEDES-BENZ 124 (C124) 03/87-> MERCEDES-BENZ E-CLASS (C124) 06/93->
TY342316	Shock Absorber	4853069445, 4853069395, 4853069705, 4853069435, 4853060140	TOYOTA LAND CRUISER 200 (J2_) 08/07->
BW342221R	Shock Absorber	31316863660, 31316777204, 31316789364, 31316863662, 31316775576	BMW 5 (F10) 09/11->
NS342251R	Shock Absorber	E4302EC85B, E4302EC80A, E4302EU51A, E4302ED00A, E4302EM30C	NISSAN TIIDA (C11) 09/07-> NISSAN TIIDA (SC11) 09/07->
NS342252L	Shock Absorber	E4303EC80A, E4303EU51A, E4303ED00A, E4303ZN90A, E4303EE90A	NISSAN TIIDA (C11) 09/07-> NISSAN TIIDA (SC11) 09/07->
LR342042R	Shock Absorber	LR031667, LR001139, LR026066	LAND ROVER FREELANDER 2 (L359) 10/06->
LR342043L	Shock Absorber	LR031665, LR001141, LR026068	LAND ROVER FREELANDER 2 (L359) 10/06->
FR342105	Shock Absorber	1805578, 1805577, 1517638, CV6Z18125P, 1704260	FORD KUGA II (DM2) 01/14-> FORD KUGA I 02/08->
FT342037	Shock Absorber	4180054PA0, 4180061M00, 4180054P01, 71747583, 71747483	SUZUKI VITARA (LY) 05/15-> SUZUKI SX4 S-CROSS (JY) 12/13->
GM342145	Shock Absorber	96626215, 96626214, 20767213, 95104355	CHEVROLET CAPTIVA (C100, C140) 03/11-> OPEL ANTARA A (L07) 12/10->
GM342194R	Shock Absorber	344655, 93188950, 344660	OPEL CORSA D (S07) 07/06-> VAUXHALL CORSA Mk III (D) (S07) 08/06->
GM342269R	Shock Absorber	344655, 93188950, 344660	OPEL CORSA D (S07) 07/06->

SHOCK ABSORBER

GM342270L	Shock Absorber	93188949, 344654, 0344654	OPEL CORSA E (X15) 09/14->
			VAUXHALL CORSA Mk III (D) (S07) 08/06->
			VAUXHALL CORSA Mk IV (E) (X15) 08/14->
			OPEL CORSA D (S07) 07/06->
GM342354R	Shock Absorber	13261197, 0344767, 13354010	VAUXHALL CORSA Mk IV (E) (X15) 08/14->
			VAUXHALL CORSA Mk III (D) (S07) 06/10->
			OPEL CORSA E (X15) 03/15->
			OPEL ASTRA J (P10) 12/09->
GM342356L	Shock Absorber	13261196, 13310101, 13310093	CHEVROLET ORLANDO (J309) 02/11->
			OPEL ASTRA J 06/12->
			OPEL ZAFIRA TOURER C (P12) 10/11->
			OPEL ASTRA J (P10) 12/09->
TY342758R	Shock Absorber	4851080821, 4851080602, 4851080647, 4851080729, 4851079305	CHEVROLET ORLANDO (J309) 02/11->
			OPEL ASTRA J 06/12->
			OPEL ZAFIRA TOURER C (P12) 10/11->
			OPEL ASTRA J (P10) 12/09->
HY342188L	Shock Absorber	54650F1030, 54650F1530, 54650F1000, 54650F1520, 54650D7000	OPEL ZAFIRA TOURER C (P12) 10/11->
			OPEL ASTRA J 06/12->
			OPEL ASTRA J (P10) 12/09->
			OPEL ASTRA J 06/12->
HY342231L	Shock Absorber	54651C5460, 54651C5450, 54651C5150, 54651C5000, 54651C5260	KIA SPORTAGE IV (QL, QLE) 12/15->
			HYUNDAI TUCSON (TL, TLE) 06/15->
			KIA SORENTO III (UM) 01/15->
			KIA SORENTO III (UM) 01/15->
HY342232R	Shock Absorber	54661C5460, 54661C5450, 54661C5260, 54661C5000, 54661C5150	KIA SORENTO III (UM) 01/15->
			KIA SORENTO III (UM) 01/15->
			KIA SORENTO III (UM) 01/15->
			KIA SORENTO III (UM) 01/15->
NS342314R	Shock Absorber	E4302JN00C, E4302JA02A, E4302JN00D, 54302JA02A, E4302ZX00A	NISSAN TEANA II (J32) 07/08->
			NISSAN (DFAC) TEANA (J32Z) 06/08->
			NISSAN ALTIMA (CL32) 09/09->
			NISSAN ALTIMA (L32) 10/06->
NS342315L	Shock Absorber	E4303JN00C, E4303JA02A, E4303JN00D, 54303JA02A, 54303JA12A	NISSAN ALTIMA (L32) 10/06->
			NISSAN (DFAC) TEANA (J32Z) 11/10->
			NISSAN ALTIMA (CL32) 04/07->
			NISSAN ALTIMA (L32) 10/06->
NS342355L	Shock Absorber	E4303BA61A, E43031KA1A, E43031KC2B, E43031KC2A, E4303BX81A	NISSAN TEANA II (J32) 07/08->
			NISSAN ALTIMA (L32) 10/06->
			NISSAN (DFAC) TEANA (J32Z) 11/10->
			NISSAN ALTIMA (CL32) 04/07->
RN342162	Shock Absorber	562107788R, 562104719R, 8200792803, 562105006R, 562101002R	NISSAN JUKE (F15) 06/10->
			RENAULT SANDERO/STEPWAY I (BS_) 12/07->
			RENAULT SANDERO/STEPWAY I (BS_) 12/07->
			RENAULT SANDERO/STEPWAY I (BS_) 12/07->
SZ342164L	Shock Absorber	4160275K00, 4160280J01, 4160280J00	SUZUKI SX4 (EY, GY) 06/06->
			SUZUKI SX4 (GY, RW) 10/07->
			SUZUKI SX4 (EY, GY) 06/06->
			SUZUKI SX4 (GY, RW) 10/07->
SZ342165R	Shock Absorber	4160175K00, 4160180J01, 4160180J00	SUZUKI SX4 (EY, GY) 06/06->
			SUZUKI SX4 (GY, RW) 10/07->
			SUZUKI SX4 (EY, GY) 06/06->
			SUZUKI SX4 (GY, RW) 10/07->
SZ342168R	Shock Absorber	4160179JA2, 4160179JF2, 71747479, 71746771, 71746769	SUZUKI SX4 (EY, GY) 07/09->
			FIAT SEDICI (189_) 06/06->
			FIAT SEDICI (189_) 06/06->
			FIAT SEDICI (189_) 06/06->
TY342304	Shock Absorber	4853080701, 4853080818, 4853069505, 4853069596, 4853069506	TOYOTA LAND CRUISER PRADO (J15_) 08/09->
			TOYOTA FJ CRUISER (GSJ1_) 06/05->
			TOYOTA FJ CRUISER (GSJ1_) 06/05->
			TOYOTA FJ CRUISER (GSJ1_) 06/05->
LA342083	Shock Absorber	8450031059, 2180291540220	LADA VESTA (GFL_) 11/15->
			LADA VESTA SW (GFK_) 11/15->
			LADA VESTA SW (GFK_) 11/15->
			LADA VESTA SW (GFK_) 11/15->
MZ342101	Shock Absorber	KN1C28700B, GMD928910D, GLK528910F, KN1C28700A, GLK528910N	MAZDA 6 (GJ, GL) 12/12->
			MAZDA CX-5 (KF) 03/19->
			MAZDA CX-5 (KF) 03/18->
			MAZDA CX-5 (KE, GH) 01/12->
MZ342096	Shock Absorber	KA0T28910F, KF1R28700A, KF4928910E, KD4528910B, KF6928910A	MAZDA CX-5 (KE, GH) 01/12->
			MAZDA CX-5 (KE, GH) 01/12->
			MAZDA CX-5 (KE, GH) 01/12->
			MAZDA CX-5 (KE, GH) 01/12->
CE342018L	Shock Absorber	T112905010, S2905700, 4852049135, S2905600, A094344027	TOYOTA RAV 4 II (A2_) 05/00->
			TOYOTA RAV 4 II (A2_) 05/00->
			TOYOTA RAV 4 II (A2_) 05/00->
			TOYOTA RAV 4 II (A2_) 05/00->
MZ342090	Shock Absorber	GS1D28700J, GS1D28700G, GS1D28700D, GS1D28700H, GS1D28700F	MAZDA 6 (GH) 08/07->
			MAZDA 6 (GH) 08/07->
			MAZDA 6 (GH) 08/07->
			MAZDA 6 (GH) 08/07->
FR342120R	Shock Absorber	1112667, 2M5Z18124AD, 1201937, 1202248, 1441938	FORD FOCUS I (DFW) 02/99->
			FORD FOCUS I (DAW, DBW) 10/98->
			FORD FOCUS I (DNW) 02/99->
			FORD FOCUS I (DNW) 02/99->
FR342121L	Shock Absorber	1112670, 1202275, 1088231, 3M5118B039CCA, 4M5118K001ABA	FORD FOCUS I (DFW) 02/99->
			FORD FOCUS I (DAW, DBW) 10/98->
			FORD FOCUS I (DNW) 02/99->
			FORD FOCUS I (DNW) 02/99->
TY342734	Shock Absorber	B2915120, 4853009J20, 4853080266, 4853009F20, 4853080170	TOYOTA COROLLA (E12_) 10/01->
			TOYOTA COROLLA Verso (E12_) 12/01->
			TOYOTA COROLLA Verso (E12_) 12/01->
			TOYOTA COROLLA Verso (E12_) 12/01->
HN342025	Shock Absorber	52610SNA903, 52610SNEA03, IHSBR048, 52610SNLT03, 52610SNAP02	HONDA CIVIC VIII (FD, FA) 09/05->
			HONDA CIVIC VIII (FD, FA) 09/05->
			HONDA CIVIC VIII (FD, FA) 09/05->
			HONDA CIVIC VIII (FD, FA) 09/05->
HN342111L	Shock Absorber	51606SMGE06, 51602SMGE19, 51606SMGB01, 51606SMGE04, 51606SMJE06	HONDA CIVIC VIII (FN, FK) 09/05->
			HONDA CIVIC VIII (FN, FK) 09/05->
			HONDA CIVIC VIII (FN, FK) 09/05->
			HONDA CIVIC VIII (FN, FK) 09/05->
HY342035	Shock Absorber	553101C200, 553101C500, 553101C000	HYUNDAI GETZ (TB) 08/05->
			HYUNDAI GETZ (TB) 08/05->
			HYUNDAI GETZ (TB) 08/05->
			HYUNDAI GETZ (TB) 08/05->
RN342072	Shock Absorber	8200779901, 6001549249, 8200750133	LADA LARGUS (KS0_, RS0_, KSA_) 09/17->
			RENAULT LOGAN I (KS_) 04/07->
			RENAULT LOGAN I (KS_) 04/07->
			RENAULT LOGAN I (KS_) 04/07->
TY342302	Shock Absorber	4853009W70, 4853009W71, 4853009Y20, 4853009W10, 4853009W20	TOYOTA COROLLA (E18_, ZRE1_) 06/13->
			TOYOTA COROLLA (E18_, ZRE1_) 06/13->
			TOYOTA COROLLA (E18_, ZRE1_) 06/13->
			TOYOTA COROLLA (E18_, ZRE1_) 06/13->
FR342205	Shock Absorber	1466421, 1673691, 1466431, 1466423, 1466428	TOYOTA AURIS (E18_) 07/13->
			FORD TRANSIT (FA_) 10/11->
			FORD TRANSIT (FD_, FB_, FS_, FZ_, FC_) 04/06->
			FORD TRANSIT (FM_, FN_, F) 10/11->
TY342609R	Shock Absorber	4851080416, 4851080418, 4851080318, 4851080527, 4851080452	FORD TRANSIT TOURNEO 07/06->
			FORD TRANSIT TOURNEO 07/06->
			FORD TRANSIT TOURNEO 07/06->
			FORD TRANSIT TOURNEO 07/06->
VL342038	Shock Absorber	8667248, 8667252, 8667253, 30760286, 8667250	TOYOTA RAV 4 III (A3_) 02/06->
			VOLVO S60 I (384) 11/00->
			VOLVO S80 I (184) 01/99->
			VOLVO V70 II (285) 03/00->
AU342068	Shock Absorber	4G0413031N, 4G0413031AD, 4G0413031AB, 4G0413031AE, 4G0413031K	VOLVO V70 I (875, 876) 04/96->
			AUDI A6 C7 (4G2, 4GC) 05/11->
			AUDI A7 (4GA, 4GF) 10/10->
			AUDI A6 C7 (4G5, 4GD) 05/15->

SHOCK ABSORBER



BW342220L	Shock Absorber	31316863661, 31316789363, 31316777203, 31316789365, 31316775575	BMW 5 (F10) 09/11->
WG342090	Shock Absorber	2K0513029N, 2K3513029E, 2K5513029R, 2K5513029S, 6K9513031A	VW CADDY III (2KB, 2KJ, 2CB, 2CJ) 04/04-> VW CADDY IV (SAB, SAJ) 11/15-> VW CADDY ALLTRACK IV (SAB) 06/15->
AU342104	Shock Absorber	8K0413031CH, 8T0413031AF, 8T0413031AE, 8F0413031P, 8T0413031L	AUDI A4 B8 (8K2) 11/11-> AUDI A5 (8T3) 05/09-> AUDI A5 (8TA) 09/09-> AUDI A4 B8 (8K5) 04/08->
SY342018	Shock Absorber	4431009003, 4431008C00, 4431032001, 4431008301, 4431008300	SSANGYONG KYRON 05/05-> SSANGYONG REXTON / REXTON II (GAB_) 06/06-> SSANGYONG ACTYON SPORTS I (QJ) 04/07-> SSANGYONG ACTYON I 11/06->
TY342272	Shock Absorber	4853080502, 4853080395, 4853080501, 485308Z045, 4853080533	TOYOTA COROLLA (_E15_) 01/07-> TOYOTA AURIS (_E15_) 03/07-> TOYOTA PRIUS (_W3_) 06/08->
GM342102	Shock Absorber	93178641, 436334, 93178642, 93178640	OPEL MERIVA A (X03) 01/06-> OPEL ZAFIRA A (T98) 09/00-> OPEL COMBO Tour 10/05-> VAUXHALL COMBO TOUR Mk II (C) (F25) 09/01->
WG342159	Shock Absorber	4B0412031CD, 8D0413031BP, 8D0413031BQ, 4B0412031BD, 4B0412031BM	VW PASSAT B5.5 (3B3) 11/00-> AUDI A4 B5 (8D2) 01/95-> SKODA SUPERB I (3U4) 12/01-> VW PASSAT B5.5 (3B6) 11/00->
HN342261	Shock Absorber	52611T1GE01, 52611T0AA02, 52611T1WA03, 52611T0AJ02, 52611T1GE51	HONDA CR-V IV (RM_) 01/12-> HONDA CR-V III (RE_) 01/07->
HY342064	Shock Absorber	55311D4130, 55311C1350, 55311D4330, 55311D4320, 55310C2520	KIA OPTIMA (JF) 09/15-> HYUNDAI SONATA VII (LF) 09/14->
NS342464	Shock Absorber	561005X01C, 56100EB39D, 56100EB31E, 56100EB31D, 561005X01A	NISSAN PATHFINDER III (R51) 01/05-> NISSAN NAVARA NP300 (D40) 07/05->
RN342087	Shock Absorber	8200415734, 8200421322, 562107002R, 8200287404, 8200400586	RENAULT SCÉNIC II (JM0/1_) 05/05-> RENAULT MEGANE II (KM0/1_) 01/06-> RENAULT GRAND SCÉNIC II (JM0/1_) 05/05->
MS342203L	Shock Absorber	A1563231700, 1563231700	MERCEDES-BENZ GLA-CLASS (X156) 12/13-> MERCEDES-BENZ A-CLASS (W176) 09/12-> MERCEDES-BENZ CLA (C117) 01/13-> MERCEDES-BENZ B-CLASS (W246, W242) 11/11->
MS342204R	Shock Absorber	A1563231800, 1563231800	MERCEDES-BENZ GLA-CLASS (X156) 12/13-> MERCEDES-BENZ A-CLASS (W176) 09/12-> MERCEDES-BENZ CLA (C117) 01/13-> MERCEDES-BENZ B-CLASS (W246, W242) 11/11->
CE342017R	Shock Absorber	T112905020, S2905200, 4852049615, S2905100, A094344028	TOYOTA RAV 4 II (_A2_) 05/00->
KI342055R	Shock Absorber	0K2ND34700, 0K2SB34700, 0K2ND34700A, 0K2SA34700, 0K2NC34700	KIA SHUMA II (FB) 05/01-> KIA CERATO I (LD) 05/06->
LA342078L	Shock Absorber	8450006745, 21802905403, 2180290540300	LADA VESTA (GFL_) 11/15->
KI342079L	Shock Absorber	0K2NB28900, 0K2SB28900A, 0K2NB28900B, 0K2NB28900A, 0K2NA28900	KIA SHUMA II (FB) 05/01->
GL342015	Shock Absorber	4020003800, 4020023900, JL718001412799	GEELY ATLAS 02/18->
LA342089	Shock Absorber	543022846R, 543020550R, 543029600R, 543027370R	LADA XRAY (GAB_) 02/16-> RENAULT SANDERO/STEPWAY II (B8_) 04/14->
MT342175R	Shock Absorber	4060A514, 4060A422, 4060A562	MITSUBISHI OUTLANDER III (GG_W, GF_W, ZJ, ZL, ZK) 10/12->
BW342215R	Shock Absorber	37106869024, 37106869026, 37106896442, 6896442, 6869024	BMW X5 (G05, F95) 08/18-> BMW X6 (G06, F96) 08/19->
NS342131	Shock Absorber	E6200ZV90A, E6210EC80A, E6210ED00A, E6210EU51A, E6210EU50A	NISSAN TIIDA (C11) 09/07-> NISSAN TIIDA (SC11) 09/07->
MS342205	Shock Absorber	A2123204630, A2123201030, A2123200630, 2123200630, A2123203930	MERCEDES-BENZ E-CLASS (W212) 01/13->
KI342144L	Shock Absorber	54650C1070, 54650C1630, 54650D4000, 54650G8000, 54650D4540	KIA OPTIMA (JF) 09/15-> HYUNDAI SONATA VII (LF) 09/14->
MS342208	Shock Absorber	A2043231900, A2043230700, A2043231700, A2043234000, A2043234200	MERCEDES-BENZ GLK-CLASS (X204) 12/08->
MS342211	Shock Absorber	A2123236500, A2123236800, A2123231400, A2123235600, A2123236000	MERCEDES-BENZ E-CLASS (S212) 12/11-> MERCEDES-BENZ E-CLASS (W212) 03/11->
BW342216	Shock Absorber	33526874369, 33526873807, 33526874377, 33526873722, 33526873775	BMW 3 (F30, F80) 07/12-> BMW 1 (F21) 12/11-> BMW 1 (F20) 07/11-> BMW 3 (F34) 07/15->
LA342080	Shock Absorber	8450009395	LADA LARGUS (KS0_, RS0_, KSA_) 03/12->
AU342088	Shock Absorber	4A0513031, 3B5513031D, 4A9513031B, 443513031N, 4A0513031C	AUDI 100 C4 (4A2) 12/90-> AUDI A6 C4 (4A2) 06/94-> AUDI 100 C4 (4A5) 09/91-> AUDI A6 C4 (4A5) 06/94->
KI342145R	Shock Absorber	54660C1630, 54660C1070, 54660D4000, 54660C1055, 54660G8000	KIA OPTIMA (JF) 09/15-> HYUNDAI SONATA VII (LF) 09/14->
NS342216	Shock Absorber	56200EB31C, 562005X01A, 56200EA525, 562005X01B, 56200EB31A	NISSAN PATHFINDER III (R51) 01/05->
NS342175	Shock Absorber	E62101DA1B, E6210JG01A, E6210JE21B, E62101DA2B, 56210BM92A	NISSAN X-TRAIL III (T32_, T32R, T32RR) 09/14-> NISSAN X-TRAIL II (T31) 06/07-> NISSAN (DFAC) QASHQAI (J10) 01/11->
KI342142R	Shock Absorber	546604H000, 546604H155, 546604H100, 546604H050, 546604H600	HYUNDAI H-1 Cargo (TQ) 08/09->

SHOCK ABSORBER

			HYUNDAI H-1 Travel (TQ) 05/08-> HYUNDAI H-1 / STAREX (A1) 06/06->
NS342261R	Shock Absorber	E43029U00D, E4302BH01A, E43029U00C, 543029U025, 543029U000	NISSAN NOTE (E11, NE11) 03/06->
KI342078R	Shock Absorber	0K2NB28700, 0K2NB28700B, 0K2NB28700A, 0K2SB28700A, 0K2SA28700A	KIA SHUMA II (FB) 05/01->
NS342262L	Shock Absorber	E4303BH01A, E43039U00D, E43039U00C, 543039U025, 543039U000	NISSAN NOTE (E11, NE11) 03/06->
MZ342071	Shock Absorber	BR5S28910C, BP4K28910D, BRY028910, BR5S28910B, BR5S28910D	MAZDA 3 (BK) 02/04->
MZ342088	Shock Absorber	GR1L28700, GR2F28700, GJ6J28700B, GJ6J28700E, GR1L28700A	MAZDA 6 (GG) 03/05-> MAZDA 6 (GY) 03/05->
MT342176L	Shock Absorber	4060A421, 4060A513, 4060A561	MITSUBISHI OUTLANDER III (GG_W, GF_W, ZJ, ZL, ZK) 10/12->
NS342177	Shock Absorber	E6210JD04A, E6210BR05A, E6210JD02A, E6210EY11A, E6210JD03B	NISSAN QASHQAI I (J10, NJ10) 02/07->
KI342141L	Shock Absorber	546504H000, 546504H155, 546504H100, 546504H050, 546504H600	HYUNDAI H-1 Cargo (TQ) 08/09-> HYUNDAI H-1 Travel (TQ) 05/08-> HYUNDAI H-1 / STAREX (A1) 06/06->
KI342146	Shock Absorber	553102W350, 553102W310, 553102W810, 553102W300, 553102P500	KIA SORENTO II (XM) 11/09-> HYUNDAI SANTA FÉ III (DM, DMA) 06/15-> HYUNDAI GRAND SANTA FÉ 06/13->
LA342079R	Shock Absorber	8450006744, 21802905402, 2180290540200	LADA VESTA (GFL_) 11/15->
MS342138	Shock Absorber	A2133201330, A2053208130, A2133200830, A2053201530, A2043261404	MERCEDES-BENZ E-CLASS (W213) 06/19-> MERCEDES-BENZ C-CLASS (W204) 01/07-> MERCEDES-BENZ C-CLASS (W205) 10/18-> MERCEDES-BENZ E-CLASS (C238) 06/19->
BW342209	Shock Absorber	33526789379, 33526789380, 33526789381, 33526863902, 33526863899	BMW 5 (F10) 09/11->
CT342216	Shock Absorber	5206TS, 5206TT, 5206VS, 1362549080, 5206LS	PEUGEOT BOXER 03/11-> FIAT DUCATO (250_) 08/06-> CITROËN JUMPER III 07/11->
BW342218R	Shock Absorber	31316796316, 31316796410, 31316796417, 6796316, 6796410	BMW X3 (F25) 09/10-> BMW X4 (F26) 04/14->
CT342163R	Shock Absorber	5202ZT, 5202XX, 5202ZW, 5202XV	CITROËN C4 GRAND PICASSO I (UA_) 10/06-> CITROËN C4 PICASSO I (UD_) 07/08-> PEUGEOT 308 CC (4B_) 06/09-> PEUGEOT 308 SW I (4E_, 4H_) 09/07->
MT342227	Shock Absorber	4162A311, 4162A429, 4162A378, 4162A363, 4162A496	MITSUBISHI OUTLANDER III (GG_W, GF_W, ZJ, ZL, ZK) 10/12-> MITSUBISHI OUTLANDER II (CW_W) 09/07->
LA342046	Shock Absorber	21230290540203, 21232905004, 21230290500400, 21230290540282	CHEVROLET NIVA (2123) 09/02->
TY342755R	Shock Absorber	4851009B20, 4851009A02, 4851009N70, 4851009800, 4851009810	TOYOTA AVENSIS (_T25_) 04/03->
TY342621L	Shock Absorber	4852009601, 4852009A00, 4852009890, 4852009880, 4852002201	TOYOTA COROLLA (_E12_) 10/01->
CT342178L	Shock Absorber	9684024980, 520869, 520871	PEUGEOT PARTNER TEPEE 04/08-> CITROËN BERLINGO MULTISPACE (B9) 04/08->
HY342171R	Shock Absorber	546602B510, 546602P650, 546602P100, 546602P600, 546601U400	KIA SORENTO II (XM) 11/09->
FR342175L	Shock Absorber	1746182, 1746177, 1746180, 1577973, 1721070	FORD S-MAX (WA6) 05/06-> FORD GALAXY II (WA6) 05/06->
FR342174R	Shock Absorber	1746160, 1746159, 1746164, 1746161, 1577907	FORD S-MAX (WA6) 05/06-> FORD GALAXY II (WA6) 05/06->
TY342637L	Shock Absorber	4852080460, 485208Z014, 485208Z167, 485208Z016, 485208Z168	LEXUS RX (_L2_) 10/15-> TOYOTA VERSO (_R2_) 04/09->
NS342293L	Shock Absorber	54303BA025, 54303AV425, E4303BA01A, 54303AW700, 54303AU525	NISSAN PRIMERA (P12) 01/02-> NISSAN PRIMERA (WP12) 03/02->
TY342620R	Shock Absorber	4851009701, 4851080103, 4851009A80, 4851009A70, 4851002201	TOYOTA COROLLA (_E12_) 10/01->
TY342754L	Shock Absorber	4852009A50, 4852009680, 4852009860, 4852009G20, 4852009650	TOYOTA AVENSIS (_T25_) 04/03->
LA342086	Shock Absorber	8450009394	LADA LARGUS (KS0_, RS0_, KSA_) 03/12->
WG342107	Shock Absorber	A112905010BA, 1H0413031A, JZW413031C, 6K0413031E, 6N0413031K	VW GOLF III (1H1) 11/91-> VW GOLF II (19E, 1G1) 08/83-> VW VENTO (1H2) 11/91-> VW JETTA II (19E, 1G2, 165) 01/84->
NS342292R	Shock Absorber	54302BA025, 54302AV425, 54302AU525, E4302BA01A, 54302AU025	NISSAN PRIMERA (P12) 01/02-> NISSAN PRIMERA (WP12) 03/02->
VL342071	Shock Absorber	31277877, 30776718, 31304066, 31200416, 30645515	VOLVO XC90 I (275) 10/02-> RENAULT VEL SATIS (BJ0_) 12/04->
WG342174R	Shock Absorber	7P6413032AJ, 7P6413032AK, 7P6413032AH, 7P6413032AL, 7P6413032AC	VW TOUAREG (7P5, 7P6) 08/10->
WG342173L	Shock Absorber	7P6413031AK, 7P6413031AH, 7P6413031AJ, 7P6413031AL, 7P6413031AC	VW TOUAREG (7P5, 7P6) 08/10->
FR342204	Shock Absorber	1466436, 1673690, 1466426, 1466420, 1466422	FORD TRANSIT (FD_, FB_, FS_, FZ_, FC_) 04/06-> FORD TRANSIT (FA_) 10/11-> FORD TRANSIT (FM_, FN_, F) 10/11-> FORD TRANSIT TOURNEO 10/11->
NS342471R	Shock Absorber	E4303JE21A, E4303JD04A, E4303BR00B, E4303JD01A, E4303JM00A	NISSAN QASHQAI I (J10, NJ10) 02/07-> NISSAN (DFAC) QASHQAI (J10) 03/08->
NS342470L	Shock Absorber	E4302JE21A, E4302JD04A, E4302BR00B, E4302JD03A, E4302BR20A	NISSAN QASHQAI I (J10, NJ10) 02/07-> NISSAN (DFAC) QASHQAI (J10) 03/08->
NS342323L	Shock Absorber	E4303JG01A, E43031DA1A, E4303BR05A, E4303JG71A, E4303BR06A	NISSAN X-TRAIL II (T31) 06/07-> RENAULT KOLEOS I (HY_) 09/08->
WG342158	Shock Absorber	1H0513031, 1H0513031D, 191513033, 191513033D, 1H0513031F	VW GOLF III (1H1) 11/91-> VW GOLF II (19E, 1G1) 08/83-> VW JETTA II (19E, 1G2, 165) 01/84-> SEAT TOLEDO I (1L2) 05/91->

SHOCK ABSORBER

NS342322R	Shock Absorber	E4302JG01A, E4302BR05A, E43021DA1A, 54302JY01B, E4302JG71A	NISSAN X-TRAIL II (T31) 06/07-> RENAULT KOLEOS I (HY_) 09/08->
HY342172L	Shock Absorber	546502B510, 546502P650, 546502P100, 546501U400, 546502P500	KIA SORENTO II (XM) 11/09->
FR342232	Shock Absorber	2193286, 1833281, 2193293, 1833284, 1839384	FORD TRANSIT V363 (FCD, FDD) 08/13-> FORD TRANSIT V363 (FED, FFD) 08/13-> FORD TRANSIT V363 (FAD, FBD) 08/13->
FR342208	Shock Absorber	1843158, 2193290, 1833282, 1833283, BK3118045HC	FORD TRANSIT V363 (FCD, FDD) 08/13-> FORD TRANSIT V363 (FED, FFD) 08/13-> FORD TRANSIT V363 (FAD, FBD) 08/13-> FORD TRANSIT CUSTOM V362 (FY, FZ) 09/12->
CT342219	Shock Absorber	5208L4, 50707867, 520841, 50707946, 50708439	PEUGEOT BOXER 03/11-> FIAT DUCATO (250_) 08/06-> CITROËN JUMPER III 07/11-> OPEL MOVANO C (U9, X250) 12/21->
CT342205	Shock Absorber	5208L2, 50707078, 5202XG, 50711998, 5208L5	PEUGEOT BOXER 03/11-> FIAT DUCATO (250_) 08/06-> CITROËN JUMPER III 07/11-> OPEL MOVANO C (U9, X250) 12/21->
CT342177R	Shock Absorber	520870, 9684025080, 520872	PEUGEOT PARTNER TEPEE 04/08-> CITROËN BERLINGO MULTISPACE (B9) 04/08->
MS342175	Shock Absorber	A1243205130, A1243203030, A2013203130, A1243203730, A1243206030	MERCEDES-BENZ 190 (W201) 10/82-> MERCEDES-BENZ E-CLASS (W124) 06/93-> MERCEDES-BENZ CЕДАН (W124) 09/85-> MERCEDES-BENZ 124 (C124) 03/87->
NS342144	Shock Absorber	E62109U00D, E6210BH01A, E62109U00C, 562109U025, E6210BC60A	NISSAN NOTE (E11, NE11) 03/06->
MS342214	Shock Absorber	A0063230200, 0063230200, A0053234200, 0053234200, A4613230100	MERCEDES-BENZ G-CLASS (W463) 04/98-> MERCEDES-BENZ G-CLASS (W461) 07/97->
GM342099	Shock Absorber	96226990, 96208557	CHEVROLET LANOS 11/05-> DAEWOO NEXIA 02/95-> DAEWOO LANOS (KLAT) 05/97-> DAEWOO ESPERO (KLEJ) 02/95->
MZ342232L	Shock Absorber	KB8M34900, KB7W34900B, KN4C34900B, KN3L34900B, KB8T34900	MAZDA CX-5 (KF) 03/18->
WG342178	Shock Absorber	5QF413031BL, 5QF413031BM, 5QF413031CL, 5QF413031CM, 5QF413031BR	VW TIGUAN (AD1, AX1) 05/16-> SKODA KODIAQ I (NS6, NS7, NV7) 10/16-> VW TIGUAN ALLSPACE (BW2, BJ2) 04/17-> AUDI Q3 (F3B) 07/18->
MZ342233R	Shock Absorber	KB8M34700, KB7W34700B, KN4C34700B, KN3L34700B, KB8T34700	MAZDA CX-5 (KF) 03/18->
TY342760L	Shock Absorber	4852080538, 485208Z182, 485208Z308, 485208Z193, 4852080535	TOYOTA CAMRY (_V7_, _VA7_, _VH7_) 05/18->
NS342387L	Shock Absorber	E43034CL1B, E4303HZ40D, 54303HL00A, 54303BM92B, 54303BM92A	NISSAN X-TRAIL III (T32_, T32R, T32RR) 02/14->
NS342386R	Shock Absorber	E43024CL1B, E4302HZ40D, 54302BM92A, E43024BF1C, E43026MA1A	NISSAN X-TRAIL III (T32_, T32R, T32RR) 02/14->
MZ342203L	Shock Absorber	B45A34900, B45A34900B, BJS734900D, BHS234900A, B45G34900A	MAZDA 3 (BM_, BN_) 10/13-> MAZDA 3 (BM, BN) 09/13->
MZ342202R	Shock Absorber	B45A34700, B45A34700B, BHS234700A, BPM534700A, BABH34700B	MAZDA 3 (BM_, BN_) 10/13-> MAZDA 3 (BM, BN) 09/13->
MZ342174L	Shock Absorber	KD4534900A, KF6934900, KA0T34900A, KR1134900, KD3534900A	MAZDA CX-5 (KE, GH) 01/12->
MZ342173R	Shock Absorber	KD4534700A, KF6934700, KA0T34700A, KD3534700A, KA0G34700A	MAZDA CX-5 (KE, GH) 01/12->
RN342174	Shock Absorber	562103964R, 562101154R, 562107298R, 8200811407, 5621000Q3K	RENAULT DUSTER (HS_) 02/12->
		RENAULT KAPTUR (H5_) 03/16->	RENAULT DUSTER (HM_) 01/18->
GW342049	Shock Absorber	2915101XGW02A, 2915370XGW02A, 2915380XGW02A, 2915901XGW02A	HAVAL JOLION SUV 01/21->
MZ342083	Shock Absorber	BJM528910B, BJM728910A, BJM528910A, BJM528910C, BJM728910B	MAZDA 3 (BM_, BN_) 10/13-> MAZDA 3 (BM, BN) 09/13->
TY342761R	Shock Absorber	485108Z322, 485108Z461, 4851080865, 485108Z335, 485108Z567	TOYOTA CAMRY (_V7_, _VA7_, _VH7_) 05/18->
LA342092	Shock Absorber	8450006786, 21802915402, 2180291540200	LADA VESTA (GFL_) 11/15-> LADA VESTA SW (GFK_) 11/15->
CE342040L	Shock Absorber	202000359AA	CHERY TIGGO 7 09/16-> EXEED (CHERY) LX 04/22-> CHERY TIGGO 7 PLUS 05/22->
CE342041R	Shock Absorber	202000360AA	CHERY TIGGO 7 09/16-> EXEED (CHERY) LX 04/22-> CHERY TIGGO 7 PLUS 05/22->
CE342042	Shock Absorber	202000362AA	CHERY TIGGO 7 09/16-> EXEED (CHERY) LX 04/22-> CHERY TIGGO 7 PLUS 09/21->
CE342037L	Shock Absorber	202001105AA	EXEED (CHERY) LX 04/22-> CHERY TIGGO 4 06/21-> CHERY TIGGO 7 03/20-> CHERY TIGGO 7 PLUS 05/22->
CE342038R	Shock Absorber	202001106AA	EXEED (CHERY) LX 04/22-> CHERY TIGGO 7 PLUS 09/21-> CHERY TIGGO 4 06/21-> CHERY TIGGO 7 03/20->
CE342039	Shock Absorber	202001603AA, 202000962AA, 202000265AA, 202001907AA, 202000961AA	CHERY TIGGO 4 09/18->
GW342047L	Shock Absorber	2905401XGW02A	HAVAL JOLION SUV 01/21->

SHOCK ABSORBER



GW342048R	Shock Absorber	2905402XGW02A	HAVAL JOLION SUV 01/21->
GW342052	Shock Absorber	2915111XKQ00A	HAVAL F7 11/18->
GL342085R	Shock Absorber	4013088600	GEELY MONJARO 01/23->
GL342084L	Shock Absorber	4013088800	GEELY MONJARO 01/23->
KI342149	Shock Absorber	55311F1000	KIA SPORTAGE IV (QL, QLE) 12/15-> HYUNDAI TUCSON (TL, TLE) 06/15-> HYUNDAI ix35 (LM, EL, ELH) 11/13-> HYUNDAI TUCSON (NX4E, NX4A) 05/21->
RN342177	Shock Absorber	562105043R	RENAULT DUSTER (HS_) 10/11-> NISSAN TERRANO (D10) 03/14-> RENAULT DUSTER (HM_) 11/21-> RENAULT OROCH 09/15->
TY342764R	Shock Absorber	485108Z384, 485108Z499, 485108Z378, 485108Z508, 4851002M10	TOYOTA COROLLA (_E21_) 01/19-> SUZUKI SWACE (AMZ_) 10/20-> TOYOTA COROLLA (_E21_, _EA1_, _EH1_) 02/19->
TY342636R	Shock Absorber	485108Z102, 4851080784, 485108Z307, 485108Z105, 485108Z103	LEXUS RX (_L2_) 10/15-> TOYOTA VERSO (_R2_) 04/09->
GW342055	Shock Absorber	2915110BKZ16A, 2915100AKZ16A	HAVAL M6 PLUS 01/21->
GL342093L	Shock Absorber	4013078100, 4013086500	GEELY COOLRAY 02/20->
GL342095	Shock Absorber	4020055000	GEELY COOLRAY 02/20->
CE342046L	Shock Absorber	202001600AA, 202001633AA	CHERY TIGGO 4 09/18->
GW342054R	Shock Absorber	2905220AKZ16A	HAVAL H2 07/14-> HAVAL H6 03/13-> HAVAL H6 COUPE 04/15->
JC342083L	Shock Absorber	2905110U7300	MOSKVICH 6 09/23->
GW342053L	Shock Absorber	2905110AKZ16A, 2905100AKZ16A	HAVAL H2 07/14-> HAVAL H6 03/13-> HAVAL H6 COUPE 04/15->
GL342092	Shock Absorber	4020049900, 8894164955	GEELY MONJARO 07/21->
CE342047R	Shock Absorber	202001601AA, 202001634AA	CHERY TIGGO 4 09/18->
JC342084R	Shock Absorber	2905210U7300	MOSKVICH 6 09/23->
GL342096L	Shock Absorber	4013056400	GEELY ATLAS 02/18->
GW342050L	Shock Absorber	2905110XKQ00A, 2905112XKQ00A	HAVAL F7X 04/19-> HAVAL F7 11/18->
GW342051R	Shock Absorber	2905113XKQ00A	HAVAL F7X 04/19-> HAVAL F7 11/18->
GL342097R	Shock Absorber	4013056100	GEELY ATLAS 02/18->
CE342050R	Shock Absorber	J682905020	GEELY ATLAS 02/18-> CHERY TIGGO 4 09/18-> OMODA C5 11/23->
GL342094R	Shock Absorber	4013078300, 4013086500	GEELY COOLRAY 02/20->
GL342098	Shock Absorber	4020056100, P8889639827	GEELY BOYUE X 10/21->
TY342763L	Shock Absorber	485208Z236, 485208Z340, 485208Z230, 485208Z237, 485208Z219	TOYOTA COROLLA (_E21_) 01/19-> SUZUKI SWACE (AMZ_) 10/20-> TOYOTA COROLLA (_E21_, _EA1_, _EH1_) 01/19->
CE342049L	Shock Absorber	J682905010	CHERY TIGGO 4 09/18-> OMODA C5 11/23->
KI342152	Shock Absorber	55310J7DA0, 55310J7BA0, 55307M7GA0, 55310J7CA0, 55310J7AA0	KIA CEED (CD) 03/18-> KIA PROCEED (CD) 10/18-> HYUNDAI i30 (PDE) 06/20-> KIA NIRO I (DE) 09/16->
GL342088R	Shock Absorber	4013048100, 4013048200	GEELY COOLRAY 02/20->
GL342087L	Shock Absorber	6600004862	GEELY COOLRAY 02/20->
GL342089	Shock Absorber	4020032700	GEELY ATLAS PRO 03/20->
GL342091R	Shock Absorber	4013099200, 4013099300	GEELY ATLAS II 12/24->
GL342090L	Shock Absorber	4013099000, 4013099100	GEELY ATLAS II 12/24->
GL342086	Shock Absorber	4020046700, SX116600001930, 116600001930	GEELY COOLRAY 02/20->
CE342043L	Shock Absorber	202000957AA	CHERY TIGGO 4 09/18-> OMODA C5 04/23->
CE342044R	Shock Absorber	202000958AA	CHERY TIGGO 4 09/18-> OMODA C5 04/23->
JC342085	Shock Absorber	2915110U3400	MOSKVICH 3 (DA21_, DA22_) 03/23->

ABSEL

Power in Motion. Quality in Parts.

HEAD OFFICE



Jebel Ali Free Zone South, Dubai, UAE
+971 4 340 0336 | +971 50 896 0071
www.absel.com
info@absel.com

MANUFACTURING COORDINATION CENTER



No:19/6 Mahmutbey, Taşocağı Yolu, Entrance C1
Office:52, Bağcılar, 34218 İstanbul, Turkey
+90 539 926 93 36 | +90 212 924 40 50
info@absel.com

TOP QUALITY



GUARANTEED



absel.com